



MX-Sensor_V1.19 Function List For US Market (Note:For reference only)

NOTES:

- This function is supported.
 - This function is not supported.
- Mark explaining (Red: New, Yellow: Modify)

Special Declaration:

- 1). If the "Relearn Type" of MX-Sensor is only OBD type, and the "OBD-II Function" has not been released for the moment, you can just do the clone for relearning the MX-Sensor.
- 2). All the Automatic Relearn Procedure for MX-Sensor, the drive speed should be controlled between 16 mph (25 km/h) and 64 mph (100 km/h).

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|--|-----------|---------------------|------------------------------|-------------------------|
| Abarth | 124 Spider | 10/2016-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Abarth | 124 Spider | 09/2016-12/2020 | 315MHz | | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Acura | CSX | 06/2005-12/2012 | 315MHz | | ● | ● | ○ | O | 315MHz | TRW | ● | ● |
| Acura | ILX | 06/2018-12/2022 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Acura | ILX | 01/2016-12/2021 | 315MHz | | ● | ● | ○ | O | 315MHz | Continental | ● | ● |
| Acura | ILX | 01/2013-12/2015 | 315MHz | | ● | ● | ○ | O | 315MHz | Continental | ● | ● |
| Acura | MDX | 01/2004-12/2006 | 315MHz | | ● | ● | ○ | O | 315MHz | TRW | ● | ● |
| Acura | MDX | 06/2013-12/2015 | 315MHz | | ● | ● | ○ | O | 315MHz | Continental | ● | ● |
| Acura | MDX | 01/2007-05/2013 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Pacific | ● | ● |
| Acura | MDX | 01/2022-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Acura | MDX | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Acura | MDX | 01/2016-12/2020 | 315MHz | | ● | ● | ○ | O | 315MHz | Continental | ● | ● |
| Acura | NSX | 01/2016-12/2022 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Acura | NSX | 06/2016-12/2020 | 315MHz | | ● | ● | ○ | O | 315MHz | Continental | ● | ● |
| Acura | RDX | 01/2013-12/2015 | 315MHz | | ● | ● | ○ | O | 315MHz | Continental | ● | ● |
| Acura | RDX | 01/2019-12/2022 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Acura | RDX | 01/2016-12/2022 | 315MHz | | ● | ● | ○ | O | 315MHz | Continental | ● | ● |
| Acura | RDX | 01/2007-12/2012 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Pacific | ● | ● |
| Acura | RL | 01/2005-12/2008 | 315MHz | | ● | ● | ○ | O | 315MHz | TRW | ● | ● |
| Acura | RL | 01/2009-12/2013 | 315MHz | | ● | ● | ○ | O | 315MHz | TRW | ● | ● |
| Acura | RLX | 01/2016-12/2020 | 315MHz 42753TZ3A51 | | ● | ● | ○ | O | 315MHz | Continental | ● | ● |
| Acura | RLX | 01/2016-12/2020 | 315MHz 42753TX4A51 | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Acura | RLX | 01/2014-12/2015 | 315MHz | | ● | ● | ○ | O | 315MHz | TRW | ● | ● |
| Acura | TL | 01/2005-12/2008 | 315MHz | | ● | ● | ○ | O | 315MHz | TRW | ● | ● |
| Acura | TL | 01/2009-10/2012 | 315MHz | | ● | ● | ○ | O | 315MHz | TRW | ● | ● |
| Acura | TL | 11/2012-12/2014 | 315MHz | | ● | ● | ○ | O/A | 315MHz | TRW | ● | ● |
| Acura | TLX | 11/2014-12/2019 | 315MHz | | ● | ● | ○ | O | 315MHz | Continental | ● | ● |
| Acura | TLX | 01/2018-12/2022 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Acura | TSX | 01/2007-12/2008 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Pacific | ● | ● |
| Acura | TSX | 01/2009-12/2014 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Pacific | ● | ● |
| Acura | ZDX | 01/2010-12/2015 | 315MHz | | ● | ● | ○ | O | 315MHz | TRW | ● | ● |
| Alfa Romeo | 159 | 07/2005-12/2016 | 433MHz | 939 | ● | ● | ○ | A | 433MHz | TRW | ● | ● |
| Alfa Romeo | 4C | 01/2012-12/2016 | 433MHz | 4C | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Alfa Romeo | 4C | 01/2017-12/2020 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------------|------------------|-----------------|---------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Alfa Romeo | 8C | 12/2006-12/2010 | 433MHz | 920 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Alfa Romeo | Brera | 01/2005-07/2012 | 433MHz | 939/946 | ● | ● | ○ | C | 433MHz | TRW | ● | ● |
| Alfa Romeo | Castello | 01/2020-12/2020 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Alfa Romeo | GTV | 01/2020-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Alfa Romeo | Giulia | 01/2016-12/2021 | 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Alfa Romeo | Giulietta | 01/2010-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Alfa Romeo | Kamal | 01/2020-12/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alfa Romeo | MiTo | 08/2013-12/2020 | 433MHz | 955 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Alfa Romeo | MiTo | 01/2008-07/2013 | 433MHz | 955 | ● | ● | ○ | O | 433MHz | TRW | ● | ● |
| Alfa Romeo | Spider | 01/2006-12/2010 | 433MHz | 939 | ○ | ● | ○ | C | 433MHz | TRW | ● | ● |
| Alfa Romeo | Stelvio | 01/2017-12/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Alpina | Alpina 6 | 01/2014-12/2016 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | Alpina 6 | 01/2018-06/2020 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | Alpina 7 | 06/2015-12/2021 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alpina | Alpina 7 | 01/2014-12/2022 | OYGTSSRE4DB 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | Alpina 7 | 01/2011-05/2015 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | Alpina 7 | 01/2006-12/2008 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | Alpina 7 | 01/2004-12/2005 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Cygnat | 01/2011-06/2018 | 433MHz | | ● | ● | ○ | A | 433MHz | Pacific | ● | ● |
| Aston Martin | DB11 | 01/2016-12/2022 | 433MHz (Huf) | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | DB11 | 01/2017-12/2019 | 315MHz | | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Aston Martin | DB11 | 01/2016-12/2022 | 433MHz | VH500 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Aston Martin | DB9 | 01/2005-12/2011 | Smartire 433MHz | | ○ | ● | ○ | C | 433MHz | Smartire | ● | ● |
| Aston Martin | DB9 | 01/2010-12/2015 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Aston Martin | DB9 | 01/2009-12/2018 | 433MHz | AM803 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | DBS | 09/2007-12/2015 | 433MHz | V12 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | DBS | 01/2008-12/2008 | 315MHz | | ○ | ● | ○ | C | 315MHz | Huf/Beru | ● | ● |
| Aston Martin | DBS | 01/2018-12/2022 | 433MHz | | ● | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Aston Martin | DBS Superleggera | 01/2018-12/2022 | HY53SE360671 AA 433MHz | VH500 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Aston Martin | DBS Superleggera | 01/2018-12/2022 | 433MHz | VH500 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Aston Martin | DBX | 10/2018-12/2021 | SCH 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Aston Martin | One-77 | 01/2011-12/2012 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Rapide | 01/2009-12/2019 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Aston Martin | Rapide | 01/2010-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Rapide S | 01/2010-12/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Rapide S | 01/2014-12/2016 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Aston Martin | Vanquish | 01/2013-12/2018 | 315MHz | | ○ | ● | ○ | C | 315MHz | Huf/Beru | ● | ● |
| Aston Martin | Vanquish | 01/2010-12/2021 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Vantage | 01/2010-12/2021 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Vantage | 01/2005-12/2011 | Smartire 433MHz | | ○ | ● | ○ | C | 433MHz | Smartire | ● | ● |
| Aston Martin | Virage | 01/2011-12/2018 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Zagato | 01/2011-08/2012 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A3 | 01/2010-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|-----------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Audi | A3 | 01/2005-12/2014 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Audi | A4 | 01/2011-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A4 | 01/2001-12/2011 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A4 | 01/2004-12/2008 | 315MHz | | ● | ● | ○ | C | 315MHz | Huf/Beru | ● | ● |
| Audi | A4 | 01/2007-12/2012 | 315MHz Continental | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Audi | A4 Avant | 01/2001-12/2008 | 433MHz | | ● | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Audi | A5 | 01/2007-12/2012 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Audi | A5 | 01/2010-12/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A5 | 01/2019-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Audi | A6 | 01/2010-12/2017 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Audi | A6 | 01/2002-12/2005 | 315MHz 4D0907275D | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | A6 | 01/2004-12/2009 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A6 | 01/2011-12/2012 | OYGTSSRE4B 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Audi | A6 | 01/2010-12/2019 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A6 | 01/2018-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A6 | 01/2004-12/2011 | 315MHz 7PP907275G | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | A6 Allroad | 07/2017-12/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A6 Allroad | 01/2010-12/2011 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A6 Allroad | 01/2006-12/2011 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | A6 Allroad | 01/2006-12/2009 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A6 Allroad | 01/2000-12/2005 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | A6 Allroad | 01/2000-12/2007 | 433MHz | 4B | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A6L | 05/2004-05/2009 | 433MHz | 4B | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A6L | 05/2004-12/2012 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | A7 | 01/2012-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A7 | 01/2009-12/2021 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A7 Quattro | 01/2012-12/2016 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A8 | 01/2010-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A8 | 11/2009-10/2017 | 433MHz | 4H/4L | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A8 | 10/2002-12/2012 | 433MHz | 4E | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A8 | 01/1999-12/2009 | 315MHz | 4E/4D | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | A8 | 01/1999-09/2002 | 433MHz | 4D | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A8 | 01/2003-12/2020 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | A8 | 01/2016-12/2021 | 433MHz 5Q0907275 | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A9 | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | Allroad Quattro | 01/2001-12/2005 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | Alltrack | 01/2017-12/2018 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | Q2 | 01/2016-12/2021 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q2 | 01/2015-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | Q3 | 07/2011-12/2022 | 433MHz | 8U | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q3 | 01/2015-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | Q4 | 09/2019-12/2022 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q5 | 01/2018-12/2022 | 433MHz | 8R | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|-------------|-----------------|------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Audi | Q5 | 01/2017-12/2019 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Audi | Q5 | 01/2010-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | Q5 | 01/2008-12/2015 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Audi | Q7 | 01/2016-12/2021 | MLB 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q7 | 01/2016-12/2020 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Audi | Q7 | 01/2010-12/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | Q7 | 01/2010-12/2015 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Audi | Q7 | 01/2010-12/2015 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q7 | 01/2005-12/2009 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q7 | 01/2005-12/2009 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | Q8 | 01/2018-12/2022 | 433MHz | 4M | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q8 | 01/2018-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | Q9 | 01/2021-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Audi | R8 | 01/2010-12/2022 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | R8 | 01/2007-12/2020 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | R8 | 01/2007-12/2009 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | R8 Race Car | 01/2013-12/2014 | 315MHz | | ● | ● | ○ | C | 315MHz | Huf/Beru | ● | ● |
| Audi | RS3 | 07/2016-12/2021 | 433MHz | 8V | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS3 | 01/2017-12/2020 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Audi | RS4 | 01/2015-12/2022 | 5Q0907275 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS4 | 01/2006-12/2009 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | RS4 | 01/2006-12/2017 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS4 | 01/2018-12/2020 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | RS5 | 01/2012-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | RS5 | 01/2017-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS5 | 01/2018-12/2020 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | RS6 | 01/2000-12/2007 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS6 | 01/2000-12/2005 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | RS6 | 01/2008-12/2011 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | RS6 | 01/2008-12/2020 | 433MHz | | ● | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Audi | RS6 | 01/2013-12/2018 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | RS6 | 01/2021-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Audi | RS7 | 01/2014-12/2020 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS7 | 01/2021-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Audi | RS7 | 01/2013-12/2018 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | RSQ8 | 12/2019-06/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Audi | S3 | 01/2015-12/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | S4 | 01/2001-12/2009 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | S4 | 01/2004-12/2009 | 315MHz | | ● | ● | ○ | C | 315MHz | Huf/Beru | ● | ● |
| Audi | S4 | 01/2010-12/2014 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Audi | S4 | 01/2010-12/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | S4 | 01/2002-12/2003 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | S5 | 01/2008-12/2014 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Audi | S5 | 01/2010-12/2017 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | S5 | 01/2018-12/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|-------------|-----------------|-----------------------|-----------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Audi | S6 | 01/2004-12/2009 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | S6 | 01/2005-12/2011 | 315MHz 7PP907275G | | ● | ● | ○ | C | 315MHz | Huf/Beru | ● | ● |
| Audi | S6 | 01/2010-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | S6 | 01/2010-12/2022 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Audi | S6 | 01/2002-12/2005 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | S7 | 01/2017-12/2020 | 433MHz | | ● | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Audi | S8 | 01/1999-09/2002 | 315MHz | D2 | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | S8 | 01/2018-12/2020 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | S8 | 01/2020-12/2020 | 433MHz | | ● | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Audi | S8 | 01/1999-09/2002 | 433MHz | D2 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | S8 | 10/2002-12/2010 | 315MHz | D3 | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | S8 | 10/2002-10/2009 | 433MHz | D3 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | S8 | 11/2009-12/2018 | 433MHz | D4 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | S8 | 01/2010-12/2017 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | S8 | 01/2012-12/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | SQ2 | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Audi | SQ5 | 01/2014-12/2019 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | SQ5 | 01/2014-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | SQ7 | 01/2016-12/2017 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Audi | TT | 01/2010-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | TT | 01/2007-12/2014 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Audi | TT | 02/2014-12/2022 | 433MHz | AU334 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | TT RS | 01/2017-12/2020 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | TT RS | 01/2017-12/2021 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | TTS | 01/2012-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | TTS | 01/2009-12/2009 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Audi | e-tron | 01/2018-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 1 Series | 07/2010-07/2019 | 433MHz | F20/F21 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | 1 Series | 01/2007-09/2010 | 433MHz | E88/E82 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 1 Series | 07/2019-12/2022 | 433MHz | F40 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 1 Series | 10/2010-12/2019 | 433MHz | F20 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 2 Series | 01/2014-12/2022 | 433MHz | F22/F23/F45/F46 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | 2 Series | 01/2014-12/2019 | HUF 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 2 Series | 11/2019-12/2022 | 433MHz | F44 | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| BMW | 2 Series | 01/2014-12/2016 | VDO 433MHz | F45/F46 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | 3 Series | 01/1998-12/2007 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 01/1999-12/2002 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 01/2005-12/2009 | OYGTSSRE4TC 433MHz | E9x | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 09/2009-12/2013 | 433MHz | E9x | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 10/2010-03/2014 | 433MHz | F30 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 01/2014-12/2019 | 433MHz | F30/F31/F35 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | 3 Series | 03/2019-12/2022 | 433MHz | G21/G28 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series GT | 01/2013-02/2014 | 433MHz | F34 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series GT | 03/2014-06/2021 | 433MHz | F34 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|----------------|-----------------|-----------------------|-------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| BMW | 3 Series Sedan | 01/2010-12/2012 | 433MHz | E9x | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series Sedan | 01/2013-02/2014 | 433MHz | F31/F32/F34 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series Sedan | 03/2014-12/2019 | 433MHz | F34 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | 3 Series Wagon | 01/2013-02/2014 | 433MHz | F31/F32/F34 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series Wagon | 03/2014-12/2019 | 433MHz | F34 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | 4 Series | 01/2005-02/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 4 Series | 09/2020-12/2022 | 433MHz | G22 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 5 Series | 03/2014-12/2016 | 433MHz | F10/F11/F18 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 5 Series | 03/2014-12/2017 | 433MHz | F07/F10/F11 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 5 Series | 01/2017-12/2022 | 433MHz | G30/G31/G38 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | 5 Series | 01/2006-12/2012 | 433MHz | E60/E61 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 5 Series | 01/1997-12/2001 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | 5 Series | 01/1997-12/2005 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 5 Series | 01/2002-12/2005 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | 5 Series | 10/2010-02/2014 | 433MHz | F10/F07/F18 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 5 Series GT | 01/2009-12/2017 | 433MHz | F10/F07 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 5 Series GT | 01/2017-12/2019 | 433MHz | G32 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | 5 Series GT | 04/2014-06/2018 | 433MHz | F07 LCI | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 5 Series GT | 01/2009-12/2010 | 433MHz | E60/E61 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 6 Series | 01/2003-12/2011 | 433MHz | E63/E64 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 6 Series | 04/2014-12/2019 | 433MHz | F12/F13/F06 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 6 Series | 01/2011-03/2014 | 433MHz | F06/F12/F13 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 6 Series GT | 09/2016-12/2022 | 433MHz | G14/G32 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | 7 Series | 10/2010-12/2015 | 433MHz | F01/F02/F04 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 7 Series | 10/2014-12/2022 | 433MHz | G11/G12 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | 7 Series | 03/2014-05/2015 | 433MHz | F01/F02 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 7 Series | 01/2006-09/2011 | 433MHz | E65/E66 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 7 Series | 01/2002-12/2005 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 7 Series | 01/1999-12/2002 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | 7 Series | 01/1994-12/2001 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 8 Series | 07/2018-12/2022 | 433MHz | G15 | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| BMW | M1 | 01/2011-12/2012 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | M2 | 01/2018-12/2022 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | M2 | 01/2017-12/2017 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | M2 | 11/2014-12/2021 | 433MHz | F87 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | M3 | 01/2002-12/2003 | 433MHz | | ● | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| BMW | M3 | 01/2019-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | M3 | 01/2014-12/2019 | 433MHz | F80 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | M3 | 01/2010-12/2013 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | M3 | 02/2002-12/2009 | OYGTSSRE4TC 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | M4 | 01/2020-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | M4 | 10/2014-12/2020 | HUF 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | M4 | 01/2014-12/2020 | 433MHz | F82/F83 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | M5 | 04/2014-12/2018 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | M5 | 09/2010-03/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|-------------|-----------------|-----------------------|-------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| BMW | M5 | 01/2006-08/2010 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | M5 | 01/2002-12/2003 | 433MHz | | ● | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| BMW | M5 | 01/2017-06/2020 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | M5 | 01/2016-12/2022 | 36106872774 433MHz | F90 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | M6 | 06/2011-12/2014 | 36106856227 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | M6 | 01/2014-12/2018 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | M6 | 01/2019-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| BMW | M6 | 01/2006-05/2011 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | M7 | 01/2019-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| BMW | M8 | 01/2019-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| BMW | Motorcycle | 01/2010-12/2019 | 433MHz | | ○ | ○ | ○ | | 433MHz | Schrader | Activate Only | ● |
| BMW | Urban Cross | 01/2020-12/2020 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| BMW | Urban X | 01/2022-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | X1 | 03/2014-12/2016 | 433MHz | E84 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X1 | 09/2008-12/2015 | OYGTSSRE4D 433MHz | E84 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X1 | 01/2015-12/2022 | 433MHz | F48/F49 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | X2 | 01/2016-12/2022 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | X3 | 01/2017-12/2022 | 433MHz | G01/G08 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | X3 | 04/2014-12/2017 | 433MHz | F25 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X3 | 01/2004-12/2005 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | X3 | 01/2004-04/2011 | 433MHz | E83 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X3 | 11/2010-03/2014 | 433MHz | F25 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X4 | 01/2014-12/2019 | 433MHz | F26 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X4 | 03/2017-12/2022 | 433MHz | G02 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | X5 | 10/2010-12/2014 | 433MHz | E70/F15 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X5 | 01/2006-12/2011 | 433MHz | E70 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X5 | 01/2000-12/2005 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X5 | 05/2013-12/2019 | 433MHz | F15/F85 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | X5 | 09/2017-12/2022 | 433MHz | G05 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | X6 | 09/2013-12/2019 | 433MHz | F16/F86 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | X6 | 09/2019-12/2022 | 433MHz | G06 | ● | ● | ○ | C | 433MHz | Schrader | ● | ● |
| BMW | X6 | 01/2008-04/2011 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | X6 | 01/2010-12/2014 | 433MHz | E71 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X6 | 01/2007-12/2011 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X6 HYBRID | 10/2008-10/2011 | 433MHz | E72 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X7 | 01/2018-12/2022 | 433MHz | G07 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | Z Series | 01/2015-12/2018 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | Z Series | 10/2010-12/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | Z Series | 01/2006-09/2010 | 433MHz | E85/E86/E89 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | Z4 | 10/2002-12/2011 | 433MHz | E86/E89 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | Z4 | 03/2019-06/2020 | 433MHz | G02 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | Z4 | 11/2018-12/2022 | 433MHz | G29 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | Z4 | 03/2014-02/2019 | 433MHz | E89 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-------------------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| BMW | Z4 | 01/2006-02/2014 | 433MHz | E89/E71 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | Z8 | 01/2003-12/2006 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| BMW | i Series | 01/2014-06/2021 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | i3 | 01/2013-06/2022 | 433MHz | I01/I12 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | i5 | 01/2020-12/2022 | 433MHz | | ● | ● | ○ | C | 433MHz | Continental | ● | ● |
| BMW | i8 | 01/2013-12/2020 | 433MHz | I01/I12 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BORGWARD | BX6 | 06/2018-12/2020 | 433MHz | | ● | ● | ○ | O | 433MHz | Dias | ● | ● |
| Bentley | Arnage | 01/2008-12/2009 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Arnage | 01/2008-09/2011 | 7PP907275F 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Azure | 01/2010-12/2015 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Azure | 01/2007-12/2009 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Bentayga | 01/2015-12/2016 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Bentayga | 01/2016-12/2021 | 433MHz 5Q0907275 | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Brooklands | 01/2008-12/2011 | 433MHz | | ● | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Bentley | Brooklands Coupe | 01/2008-06/2016 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental | 01/2003-12/2004 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental | 01/2005-05/2005 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental | 06/2005-12/2005 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental | 01/2006-12/2011 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental | 01/2012-12/2020 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental Flying Spur | 03/2005-06/2020 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental Flying Spur | 01/2009-12/2011 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Bentley | Continental GT | 04/2018-12/2022 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental GT | 09/2003-05/2005 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental GT | 01/2005-12/2005 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Bentley | Continental GT | 06/2005-12/2021 | 433MHz BY634 | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental GT | 01/2010-01/2014 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Bentley | Continental GTC | 01/2006-12/2020 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Bentley | Flying Spur | 01/2005-12/2010 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Bentley | Flying Spur | 01/2019-12/2022 | 5Q0907275 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Bentley | Flying Spur | 01/2005-12/2010 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Flying Spur | 01/2011-12/2015 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Bentley | Flying Spur | 01/2011-12/2022 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | GTC | 07/2006-06/2020 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Mulsanne | 01/2012-12/2012 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Bentley | Mulsanne | 01/2013-12/2015 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Mulsanne | 01/2016-12/2016 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Mulsanne | 01/2017-12/2021 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Mulsanne | 01/2001-12/2020 | 7PP907275F 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Mulsanne | 01/2009-12/2009 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Mulsanne | 01/2011-12/2012 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|----------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Bentley | Mulsanne | 01/2011-12/2020 | 433MHz 95560602100 | | ● | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Bugatti | Chiron | 01/2016-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bugatti | Royale | 01/2016-12/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bugatti | Veyron | 01/2013-12/2015 | 315MHz | | ○ | ● | ○ | C | 315MHz | Huf/Beru | ● | ● |
| Bugatti | Veyron | 01/2005-12/2015 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Buick | Allure | 01/2006-12/2006 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Buick | Allure | 01/2011-12/2015 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Buick | Allure | 01/2010-12/2010 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Buick | Allure | 01/2009-12/2009 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Buick | Allure | 01/2008-12/2009 | 315MHz 13598771 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Buick | Allure | 01/2008-12/2008 | 315MHz | | ● | ● | ● | O/S | 315MHz | Continental | ● | ● |
| Buick | Allure | 01/2006-12/2007 | 315MHz | | ● | ● | ● | O/S | 315MHz | Continental | ● | ● |
| Buick | Cascada | 01/2016-12/2016 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Buick | Cascada | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Buick | Cascada | 01/2017-12/2019 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Buick | Century | 01/1999-12/2005 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Buick | Enclave | 01/2019-12/2022 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Buick | Enclave | 01/2018-12/2018 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Buick | Enclave | 01/2017-12/2018 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Buick | Enclave | 01/2017-12/2017 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Buick | Enclave | 01/2016-12/2016 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Buick | Enclave | 06/2014-12/2016 | 315MHz 23445327 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Buick | Enclave | 09/2013-12/2016 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Buick | Enclave | 09/2013-12/2015 | 315MHz 25920615 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Buick | Enclave | 01/2013-08/2013 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Buick | Enclave | 01/2009-08/2013 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Buick | Enclave | 05/2007-12/2008 | 315MHz | | ● | ● | ● | O/S | 315MHz | Continental | ● | ● |
| Buick | Encore | 01/2018-12/2022 | 315MHz 13522628 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Buick | Encore | 01/2019-12/2022 | 433MHz | GX | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Buick | Encore | 01/2017-12/2017 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Buick | Encore | 01/2016-12/2016 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Buick | Encore | 01/2013-12/2015 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Buick | Envision | 01/2021-12/2022 | 433MHz 13593957 | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Buick | Envision | 01/2020-12/2022 | 433MHz 13538566 | | ● | ● | ○ | S | 433MHz | Baolong | ● | ● |
| Buick | Envision | 01/2016-12/2022 | 315MHz 13516164 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Buick | Envision | 01/2016-12/2017 | 315MHz 13598772 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Buick | Envision | 01/2015-12/2015 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Buick | LaCrosse | 01/2009-07/2009 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Buick | LaCrosse | 01/2017-12/2020 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Buick | LaCrosse | 01/2017-12/2019 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Buick | LaCrosse | 01/2016-12/2016 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Buick | LaCrosse | 01/2016-12/2016 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Buick | LaCrosse | 01/2014-12/2015 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Buick | LaCrosse | 01/2013-12/2013 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Buick | LaCrosse | 01/2012-12/2012 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Buick | LaCrosse | 01/2011-12/2011 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Buick | LaCrosse | 08/2009-12/2010 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Buick | LaCrosse | 01/2008-07/2009 | 315MHz 13898771 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Buick | LaCrosse | 01/2008-12/2008 | 315MHz | | ● | ● | ● | O/S | 315MHz | Continental | ● | ● |
| Buick | LaCrosse | 01/2008-12/2008 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Buick | LaCrosse | 01/2007-12/2007 | 315MHz | | ● | ● | ● | O/S | 315MHz | Continental | ● | ● |
| Buick | LaCrosse | 01/2006-12/2006 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Buick | LeSabre | 01/1998-12/2005 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Buick | LeSabre | 01/2007-12/2007 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Buick | Lucerne | 01/2009-12/2011 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Buick | Lucerne | 01/2007-12/2007 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Buick | Lucerne | 01/2006-12/2006 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Buick | Lucerne | 01/2008-12/2008 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Buick | Park Avenue | 01/2006-12/2008 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Buick | Park Avenue | 01/1997-12/2005 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Buick | Park Avenue | 01/2009-12/2012 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Buick | Rainier | 01/2007-12/2007 | Snap in 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Buick | Rainier | 01/2006-12/2009 | Clamp in 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Buick | Rainier | 01/2006-12/2007 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Buick | Regal | 08/2017-12/2020 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Buick | Regal | 05/2009-12/2012 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Buick | Regal | 01/2017-12/2019 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Buick | Regal | 01/2016-12/2016 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Buick | Regal | 01/2014-12/2015 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Buick | Regal | 01/1997-12/2004 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Buick | Regal | 01/2013-12/2013 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Buick | Rendezvous | 01/2003-12/2007 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Buick | Verano | 01/2016-12/2020 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Buick | Verano | 01/2013-12/2015 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Buick | Verano | 01/2012-12/2012 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| CMC | A180 | 07/2016-12/2019 | 433MHz | | ● | ● | ○ | O | 433MHz | Orange | ● | ● |
| CMC | A190 | 07/2016-12/2019 | 433MHz | | ● | ● | ○ | O | 433MHz | Orange | ● | ● |
| CMC | VERYCA | 07/2016-06/2019 | 433MHz | | ● | ● | ○ | C | 433MHz | Schrader | ● | ● |
| CMC | ZINGER | 07/2016-06/2019 | 433MHz | | ● | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Cadillac | ATS | 01/2013-12/2013 | 315MHz | | ● | ● | ● | O/S | 315MHz | Continental | ● | ● |
| Cadillac | ATS | 01/2013-12/2014 | 315MHz 20964159 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | ATS | 01/2013-12/2020 | 315MHz 13581558 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-----------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Cadillac | ATS | 01/2015-12/2017 | 315MHz 13598772 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | ATS | 01/2016-12/2017 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | ATS | 01/2016-12/2017 | 315MHz 13598786 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | ATS | 01/2018-06/2019 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | ATS | 01/2020-12/2020 | 433MHz 13529770 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | ATS | 01/2018-12/2019 | 315MHz 13598786 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | ATS | 01/2020-12/2020 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | ATS | 01/2018-12/2019 | 315MHz 13598772 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | ATS | 01/2015-12/2020 | 315MHz 20964159 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | ATS Sport | 01/2013-12/2015 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | ATS-L | 01/2014-12/2018 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | ATS-V | 01/2016-12/2017 | 315MHz 13598786 | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | ATS-V | 01/2016-12/2019 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Cadillac | ATS-V | 01/2018-12/2019 | 315MHz 13598786 | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | ATS-V | 01/2018-12/2019 | 315MHz 13598772 | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | ATS-V | 01/2013-12/2015 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | ATS-V | 01/2016-12/2016 | 315MHz | | ○ | ● | ○ | S | 315MHz | Continental | ● | ● |
| Cadillac | CT4 | 01/2020-12/2022 | 433MHz 13593957 | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Cadillac | CT4 | 01/2020-12/2020 | 433MHz | | ● | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Cadillac | CT4 | 01/2020-12/2022 | 433MHz 13530661 | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Cadillac | CT5 | 01/2020-12/2022 | 433MHz 13530661 | | ● | ● | ○ | O/S/A | 433MHz | Schrader | ● | ● |
| Cadillac | CT5 | 01/2020-12/2022 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | CT6 | 01/2019-12/2022 | 433MHz 13516165 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | CT6 | 01/2019-12/2020 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CT6 | 01/2016-12/2021 | 433MHz 13598773 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | CT6 | 01/2016-12/2018 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2014-12/2014 | Clamp in 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2013-12/2013 | Clamp in 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2013-12/2013 | Snap in 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2012-12/2012 | Snap in 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2012-12/2012 | Clamp in 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2010-12/2011 | Clamp in 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|---------------|-----------------|--------------------|-------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Cadillac | CTS | 01/2010-12/2011 | Snap in 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2014-12/2014 | Snap in 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2016-12/2020 | 315MHz 13598772 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2016-12/2019 | 315MHz 13598786 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2016-12/2019 | 433MHz 13598787 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2014-12/2015 | 315MHz 20964159 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2009-12/2012 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2014-12/2015 | 315MHz 13581558 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2009-12/2009 | Clamp in 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2009-12/2009 | Snap in 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2008-12/2008 | 433MHz | GMX206/ GMX226 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 10/2007-12/2008 | Snap in 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2007-09/2007 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2006-12/2006 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2004-12/2005 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS-V | 01/2009-12/2013 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS-V | 01/2014-12/2016 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS-V | 01/2018-12/2019 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS-V | 01/2017-12/2019 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS-V | 01/2017-12/2017 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS-V | 01/2016-12/2016 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS-V (Sport) | 01/2015-12/2016 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS-V (Sport) | 01/2017-12/2019 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS-V (Sport) | 01/2014-12/2015 | 315MHz 15268606 | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | DTS | 01/2009-12/2011 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | DTS | 01/2008-12/2008 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | DTS | 01/2007-12/2007 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | DTS | 01/2006-12/2006 | 315MHz 25920615 | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | DTS | 01/2005-12/2006 | 315MHz 15268606 | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | Deville | 01/2005-12/2005 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | Deville | 01/2004-12/2004 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | Deville | 01/2000-12/2003 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | ELR | 01/2016-12/2016 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | ELR | 01/2017-12/2018 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | ELR | 01/2014-12/2016 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2005-12/2006 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2017-12/2020 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-----------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Cadillac | Escalade | 01/2021-12/2022 | 433MHz 13533166 | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2021-12/2021 | 433MHz 13530661 | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2018-12/2019 | 433MHz 13516165 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2015-12/2018 | 433MHz 13598773 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2013-12/2013 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2004-12/2004 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2015-12/2016 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2014-12/2014 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2010-12/2011 | Clamp in 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2007-12/2007 | Clamp in 315MHz | | ● | ● | ● | O/S | 315MHz | TRW | ● | ● |
| Cadillac | Escalade | 01/2012-12/2012 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2009-12/2011 | Snap in 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2008-12/2008 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2007-12/2007 | Snap in 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | Hearse | 01/2001-12/2005 | 315MHz | | ● | ● | ○ | C | 315MHz | Schrader | ● | ● |
| Cadillac | Limousine | 01/2001-12/2005 | 315MHz | | ● | ● | ○ | C | 315MHz | Schrader | ● | ● |
| Cadillac | SLS | 01/2012-12/2013 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | SLS | 01/2010-12/2011 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | SLS | 01/2009-12/2009 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | SLS | 01/2006-12/2008 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | SRX | 01/2004-12/2006 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | SRX | 01/2009-12/2009 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | SRX | 01/2005-12/2006 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | SRX | 01/2010-12/2011 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | SRX | 01/2010-12/2014 | 433Mhz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Cadillac | SRX | 01/2016-12/2018 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | SRX | 01/2015-12/2016 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | SRX | 01/2014-12/2015 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | SRX | 10/2012-12/2013 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | SRX | 01/2012-09/2012 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | SRX | 01/2007-12/2008 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | STS | 01/2011-12/2011 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | STS | 01/2010-12/2010 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | STS | 01/2009-12/2011 | Snap in 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | STS | 01/2009-12/2011 | 433Mhz 13598773 | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Cadillac | STS | 01/2009-12/2009 | 433Mhz 20925925 | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Cadillac | STS | 01/2008-12/2008 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | STS | 01/2004-12/2007 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|-----------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Cadillac | STS | 01/2009-12/2011 | Clamp in 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | Seville | 01/2001-12/2003 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | Seville | 01/2004-12/2004 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | XLR | 01/2010-12/2011 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | XLR | 01/2006-12/2009 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | XLR | 01/2004-12/2005 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | XLR-V | 01/2006-12/2008 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Cadillac | XT4 | 01/2020-12/2021 | 315Mhz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | XT4 | 06/2018-12/2022 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | XT5 | 01/2018-12/2022 | 433MHz 13516165 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | XT5 | 01/2018-06/2020 | 315MHz 13516164 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | XT5 | 01/2017-12/2019 | 315MHz 13589597 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | XT5 | 01/2016-06/2021 | 433MHz 13598773 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | XT6 | 01/2019-12/2022 | 315MHz 13516164 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | XT6 | 01/2019-12/2022 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | XTS | 01/2015-12/2020 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | XTS | 01/2015-12/2015 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | XTS | 01/2017-12/2019 | 315MHz 13598772 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | XTS | 01/2013-12/2014 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Avalanche | 01/2012-12/2013 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Avalanche | 01/2011-12/2013 | 433Mhz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Chevrolet | Avalanche | 01/2010-12/2011 | Clamp in 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Avalanche | 01/2009-12/2011 | Snap in 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Avalanche | 01/2008-12/2008 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Avalanche | 01/2007-12/2007 | Clamp in 315MHz | | ● | ● | ● | 0/S | 315MHz | TRW | ● | ● |
| Chevrolet | Avalanche | 01/2007-12/2007 | Snap in 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Avalanche | 01/2005-12/2006 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Avalanche | 01/2004-12/2004 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Aveo | 01/2002-12/2007 | 315MHz | | ○ | ● | ○ | C | 315MHz | Schrader | ● | ● |
| Chevrolet | Aveo | 01/2018-12/2022 | 315MHz | | ○ | ● | ○ | C | 315MHz | Schrader | ● | ● |
| Chevrolet | Aveo | 01/2012-12/2012 | 315MHz | | ● | ● | ● | 0 | 315MHz | Schrader | ● | ● |
| Chevrolet | Aveo | 01/2011-12/2011 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Chevrolet | Aveo | 01/2008-12/2010 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Chevrolet | Blazer | 01/2019-12/2021 | 433MHz | | ○ | ● | ● | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Blazer | 01/2018-12/2022 | 315MHz | | ○ | ● | ● | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Bolt EV | 01/2017-12/2018 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Bolt EV | 01/2022-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Chevrolet | Bolt EV | 01/2019-12/2021 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|------------|-----------------|-----------------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Chevrolet | Bolt EV | 01/2019-12/2020 | 433MHz 13516165 | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Chevrolet | Bolt EV | 01/2017-12/2020 | 433MHz 13598773 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2017-12/2020 | Snap in 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2013-12/2013 | 315MHz 12768826 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2012-12/2013 | 315MHz 20964159 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2012-12/2013 | 433MHz 13598773 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2012-12/2012 | 315MHz 12768826 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2010-12/2011 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2010-12/2011 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2020-12/2022 | 315Mhz | | ● | ● | ● | 0 | 315MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2014-12/2015 | 315MHz 20964159 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2018-12/2019 | 315MHz 13598786 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2020-12/2020 | 433MHz (13516 165) | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2014-12/2015 | 315MHz 22854866 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2020-12/2020 | Clamp in 433MHz | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2014-12/2015 | 433MHz 13598773 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2016-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2016-12/2016 | Snap in 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2016-12/2016 | Clamp in 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2017-12/2022 | Clamp in 433MHz (13598 787) | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro ZL1 | 01/2017-12/2021 | 433MHz 13598787 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro ZL1 | 01/2016-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Camaro ZL1 | 01/2014-12/2015 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Camaro ZL1 | 01/2012-12/2013 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Camaro ZL1 | 01/2017-12/2021 | 433MHz 13598773 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Caprice | 01/2017-12/2019 | 315MHz 13598772 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Caprice | 01/2016-12/2017 | 315MHz 13598786 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Caprice | 01/2014-12/2017 | 315MHz 13581559 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Caprice | 01/2011-12/2013 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Caprice | 01/2010-12/2015 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Caprice | 01/2007-12/2009 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|---------------|-----------------|-----------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Chevrolet | Captiva | 01/2012-12/2015 | 315MHz Clamp in | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Captiva | 12/2008-12/2019 | 315MHz Snap in | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Captiva sport | 01/2008-12/2015 | 315MHz 13598771 | | ○ | ● | ○ | C | 315MHz | Schrader | ● | ● |
| Chevrolet | Cavalier | 01/2016-12/2020 | Lo Line 433MHz | | ● | ● | ○ | O | 433MHz | Dias | ● | ● |
| Chevrolet | Cavalier | 01/2016-12/2020 | Hi Line 433MHz | | ● | ● | ○ | O/S | 433MHz | Dias | ● | ● |
| Chevrolet | Cheyenne | 01/2014-12/2014 | 315MHz | | ● | ● | ● | O | 315MHz | Schrader | ● | ● |
| Chevrolet | Cheyenne | 01/2010-12/2011 | Clamp in 315MHz | | ○ | ● | ○ | C | 315MHz | Schrader | ● | ● |
| Chevrolet | Cheyenne | 01/2007-12/2013 | Snap in 315MHz | | ○ | ● | ○ | C | 315MHz | Schrader | ● | ● |
| Chevrolet | Cheyenne | 01/2007-12/2012 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Cheyenne | 01/2015-10/2016 | 315MHz | | ● | ● | ● | O | 315MHz | Schrader | ● | ● |
| Chevrolet | Cheyenne | 01/2011-12/2015 | 433Mhz 13598773 | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Chevrolet | Cheyenne | 01/2016-12/2018 | 433MHz 13598773 | | ● | ● | ● | O | 433MHz | Schrader | ● | ● |
| Chevrolet | Cheyenne | 11/2016-12/2019 | 315MHz | | ● | ● | ● | O | 315MHz | Schrader | ● | ● |
| Chevrolet | Cheyenne | 01/2018-12/2021 | 433MHz 13516165 | | ● | ● | ● | O | 433MHz | Schrader | ● | ● |
| Chevrolet | Cheyenne | 01/2020-12/2021 | 433MHz 13512347 | | ● | ● | ● | O | 433MHz | Schrader | ● | ● |
| Chevrolet | Cheyenne | 01/2021-12/2021 | 433MHz 13530661 | | ● | ● | ● | O | 433MHz | Schrader | ● | ● |
| Chevrolet | Cheyenne DRW | 01/2017-12/2019 | 315MHz | | ○ | ● | ○ | C | 315MHz | Schrader | ● | ● |
| Chevrolet | Cheyenne DRW | 01/2017-12/2019 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Chevrolet | Cheyenne DRW | 01/2015-12/2016 | 315MHz | | ○ | ● | ○ | C | 315MHz | Schrader | ● | ● |
| Chevrolet | City Express | 01/2015-12/2018 | 315MHz | | ● | ● | ○ | O | 315MHz | Schrader | ● | ● |
| Chevrolet | Cobalt | 01/2009-12/2009 | Snap in 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Cobalt | 01/2008-12/2008 | Clamp in 315MHz | | ● | ● | ● | O/S | 315MHz | Continental | ● | ● |
| Chevrolet | Cobalt | 01/2008-12/2008 | Snap in 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Cobalt | 01/2010-12/2010 | Snap in 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Cobalt | 01/2010-12/2010 | Clamp in 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Cobalt | 01/2009-12/2009 | Clamp in 315MHz | | ● | ● | ● | O/S | 315MHz | Continental | ● | ● |
| Chevrolet | Colorado | 01/2020-12/2022 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Colorado | 01/2016-12/2016 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Colorado | 01/2015-12/2015 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Colorado | 01/2014-12/2014 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Colorado | 01/2012-12/2012 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Colorado | 01/2011-12/2011 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Colorado | 01/2020-12/2021 | 433MHz 13512347 | | ● | ● | ● | O | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|----------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Chevrolet | Colorado | 01/2007-12/2010 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Colorado | 01/2017-12/2019 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2010-12/2014 | 433MHz | C6 | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2010-12/2011 | 315MHz | C6 | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2009-12/2009 | 315MHz 13598771 | C6 | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2005-12/2009 | 315MHz 25758220 | C6 | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 06/2004-12/2009 | C6 433MHz | GMX245 | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2003-12/2004 | 315MHz | C5 | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2001-12/2002 | 315MHz | C5 | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/1997-12/2000 | 315MHz | C5 | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 02/2020-12/2022 | 433MHz | Y2XC | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2020-12/2022 | 433MHz 13593957 | | ○ | ● | ○ | S/A | 433MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2016-12/2019 | 315MHz 13581559 | C7 | ● | ● | ● | O/S/A | 315MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2015-12/2019 | 433MHz 13348393 | C7 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2015-12/2019 | 433MHz 13581560 | C7 | ● | ● | ● | O/S/A | 433MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2014-12/2015 | 315Mhz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2014-12/2014 | 433MHz | C7 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2013-12/2013 | 315MHz | C6 | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2012-12/2012 | 315MHz | C6 | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Corvette Grand | 01/2017-12/2018 | 315MHz | | ● | ● | ● | O/A | 315MHz | Schrader | ● | ● |
| Chevrolet | Cruze | 01/2020-12/2020 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Cruze | 01/2019-12/2020 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Cruze | 01/2017-12/2018 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Cruze | 01/2016-06/2019 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Cruze | 01/2016-12/2016 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Cruze | 01/2013-12/2015 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Cruze | 01/2012-12/2012 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Cruze | 01/2011-12/2011 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Equinox | 01/2017-05/2017 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Equinox | 01/2016-12/2016 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Equinox | 06/2017-12/2021 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Equinox | 06/2012-12/2014 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Equinox | 01/2011-12/2012 | 315MHz 12768826 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Equinox | 01/2010-12/2012 | 315MHz 15921013 | | ○ | ● | ○ | S | 315MHz | Continental | ● | ● |
| Chevrolet | Equinox | 01/2010-12/2010 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Equinox | 01/2009-12/2009 | 315MHz Snap in | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Equinox | 01/2009-12/2009 | 315MHz Clamp in | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Equinox | 01/2008-12/2008 | 315MHz Snap in | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|----------------|-----------------|-------------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Chevrolet | Equinox | 01/2008-12/2008 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Equinox | 01/2007-12/2007 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Equinox | 01/2013-12/2015 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Express Series | 01/2018-12/2020 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Express Series | 01/2017-12/2017 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Express Series | 01/2016-12/2017 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Express Series | 01/2014-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Express Series | 01/2009-12/2011 | 315MHz 25920615 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Express Series | 01/2009-12/2009 | 315MHz 15921013 | | ● | ● | ● | 0/S | 315MHz | Continental | ● | ● |
| Chevrolet | Express Series | 01/2018-12/2022 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Express Series | 06/2007-12/2008 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Continental | ● | ● |
| Chevrolet | Express Series | 01/2012-12/2013 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | G Series | 01/2008-12/2008 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Chevrolet | HHR | 01/2009-12/2010 | Clamp in 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | HHR | 01/2009-12/2009 | Snap in 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | HHR | 01/2008-12/2008 | Clamp in 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | HHR | 06/2007-12/2008 | Snap in 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | HHR | 01/2010-12/2011 | Snap in 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Impala | 01/2012-12/2012 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Impala | 01/2013-09/2013 | 315MHz 22854866 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Impala | 10/2013-12/2014 | Limited 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Impala | 10/2013-12/2014 | 315MHz 22854866 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Impala | 01/2014-06/2020 | 433MHz 13598773 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Impala | 01/2015-12/2015 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Impala | 01/2016-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Impala | 01/2015-12/2016 | Limited 315MHz 23445327 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Impala | 01/2015-12/2016 | Limited 315MHz 13598771 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Impala | 01/2007-12/2007 | Snap in 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Impala | 01/2008-12/2008 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Impala | 01/2020-12/2020 | 315MHz 13516164 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Impala | 01/2020-12/2020 | 433MHz 13516165 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Impala | 01/2017-06/2020 | 315MHz 13598772 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|--------------|-----------------|-----------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Chevrolet | Impala | 01/2017-12/2018 | 315MHz 23445327 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Impala | 01/2013-09/2013 | 315MHz 13598771 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Impala | 01/2007-12/2007 | Clamp in 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Impala | 01/2006-12/2006 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Impala | 01/2006-12/2006 | Clamp in 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Impala | 01/2000-12/2005 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Chevrolet | Impala | 01/2009-12/2011 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2010-06/2011 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2008-12/2008 | Clamp in 315MHz | | ● | ● | ● | O/S | 315MHz | Continental | ● | ● |
| Chevrolet | Malibu | 01/2008-12/2008 | Snap in 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2009-12/2009 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2019-12/2022 | 315MHz 13516164 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 07/2012-12/2012 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 07/2012-12/2012 | 433MHz | V300 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 07/2011-06/2012 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2019-12/2021 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2017-12/2022 | 433MHz | V300 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2017-12/2019 | 315MHz 22854866 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2017-12/2018 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2016-12/2016 | 315MHz 23445327 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2016-12/2016 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2016-12/2016 | 315MHz 25920615 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 07/2011-06/2012 | 433MHz | V300 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2015-12/2016 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 07/2014-12/2015 | 433MHz | V300 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2013-12/2014 | 315MHz 22854866 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2013-06/2014 | 433MHz | V300 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2013-12/2013 | 315MHz 25920615 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Malibu Fleet | 01/2015-12/2015 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Malibu Fleet | 01/2016-12/2018 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Monte Carlo | 01/2007-12/2007 | Snap in 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Monte Carlo | 01/2007-12/2007 | Clamp in 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Monte Carlo | 01/2000-12/2005 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Chevrolet | Monte Carlo | 01/2006-12/2006 | Snap in 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Monte Carlo | 01/2006-12/2006 | Clamp in 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|-------------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Chevrolet | Onix | 08/2014-12/2019 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Onix | 01/2019-12/2020 | 26689967 433MHz | | ● | ● | ● | O/S | 433MHz | Dias | ● | ● |
| Chevrolet | Optra | 01/2007-12/2009 | 315MHz | | ● | ● | ○ | O | 315MHz | Schrader | ● | ● |
| Chevrolet | Orlando | 01/2013-12/2015 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Orlando | 01/2012-12/2012 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Orlando | 01/2017-12/2018 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Prisma | 08/2014-12/2019 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | S10 | 01/2017-12/2019 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Chevrolet | SS Sedan | 01/2013-12/2016 | 315MHz 13581559 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | SS Sedan | 01/2014-12/2016 | 315MHz 20964159 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | SS Sedan | 01/2017-12/2017 | 315MHz 13581559 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | SS Sedan | 01/2017-12/2018 | 315MHz 20964159 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | SSR | 01/2006-12/2007 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Chevrolet | SSR | 01/2006-12/2007 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 11/2016-12/2019 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 01/2017-12/2018 | 433MHz 13598773 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 01/2017-12/2021 | 433MHz 13516165 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 01/2021-12/2021 | 433MHz 13530661 | | ● | ● | ● | O | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 01/2015-10/2016 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 01/2021-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 10/2013-12/2014 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 01/2004-12/2004 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 01/2005-12/2006 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 01/2007-12/2007 | Snap in 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 01/2007-12/2007 | Clamp in 315MHz | | ● | ● | ● | O/S | 315MHz | TRW | ● | ● |
| Chevrolet | Silverado | 01/2008-12/2008 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 01/2009-12/2011 | Clamp in 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 01/2009-09/2013 | Snap in 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 01/2011-12/2012 | 433Mhz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 01/2015-12/2016 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado DRW | 01/2015-12/2016 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Silverado DRW | 01/2017-12/2019 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado DRW | 01/2017-12/2019 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Silverado Trailer | 01/2019-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Chevrolet | Sonic | 01/2013-12/2014 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Sonic | 01/2015-12/2016 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Sonic | 01/2017-12/2021 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|----------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Chevrolet | Sonic | 01/2012-12/2012 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Spark | 01/2012-12/2014 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Spark | 01/2015-12/2015 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Spark | 01/2016-12/2016 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Spark | 01/2017-12/2022 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Spin | 08/2014-12/2019 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2016-08/2016 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2004-12/2004 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 09/2016-12/2020 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2018-12/2021 | 433MHz 13516165 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2021-12/2021 | 433MHz 13530661 | | ● | ● | ● | O | 433MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2021-12/2022 | 433MHz 13533166 | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2005-12/2006 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2007-12/2007 | Clamp in 315MHz | | ● | ● | ● | O/S | 315MHz | TRW | ● | ● |
| Chevrolet | Suburban | 01/2007-12/2007 | Snap in 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2008-12/2008 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2009-12/2013 | Snap in 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2009-12/2013 | clamp in 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2011-12/2018 | 433MHz 13598773 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2014-12/2014 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2015-12/2015 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2016-12/2018 | 433MHz 13598773 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2018-12/2019 | 433MHz 13516165 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2020-12/2021 | 315MHz 13538759 | | ○ | ● | ○ | C | 315MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2021-12/2021 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2021-12/2022 | 433MHz 13533166 | | ○ | ● | ● | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2017-12/2020 | 315MHz 13516164 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2016-12/2016 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2015-12/2015 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2014-12/2014 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2011-12/2015 | 433Mhz 13598773 | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2010-12/2011 | Clamp in 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2009-12/2013 | Snap in 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2008-12/2008 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2007-12/2007 | Clamp in 315MHz | | ● | ● | ● | O/S | 315MHz | TRW | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|-------------|-----------------|-----------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Chevrolet | Tahoe | 01/2007-12/2007 | Snap in 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2005-12/2006 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2004-12/2004 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Tracker | 01/2015-12/2022 | 433MHz | | ● | ● | ● | O | 433MHz | Schrader | ● | ● |
| Chevrolet | TrailBlazer | 01/2020-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Chevrolet | TrailBlazer | 01/2017-12/2020 | 433MHz 13598773 | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Chevrolet | Trailblazer | 01/2007-12/2009 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Trailblazer | 01/2006-12/2006 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Traverse | 01/2009-12/2013 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Traverse | 01/2018-12/2022 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Traverse | 01/2018-12/2019 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Traverse | 01/2016-12/2017 | 315MHz 13598771 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Traverse | 01/2016-12/2016 | 315MHz 13581558 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Traverse | 06/2014-12/2016 | 315MHz 23445327 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Traverse | 01/2014-12/2017 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Traverse | 01/2014-12/2015 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Traverse | 01/2013-12/2013 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Trax | 01/2019-12/2022 | 315MHz 13516164 | | ○ | ● | ○ | C | 315MHz | Schrader | ● | ● |
| Chevrolet | Trax | 01/2013-12/2014 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Trax | 01/2015-12/2015 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Trax | 01/2016-12/2016 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Trax | 01/2017-06/2021 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Uplander | 01/2008-12/2009 | 315MHz 13598771 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Uplander | 01/2008-12/2009 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Van | 01/2008-12/2011 | 315MHz | | ○ | ● | ○ | S | 315MHz | Continental | ● | ● |
| Chevrolet | Volt | 01/2013-12/2014 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Volt | 01/2017-06/2020 | 433MHz 13598773 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Volt | 01/2019-12/2019 | 433MHz 13512347 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Volt | 01/2010-12/2010 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Volt | 01/2011-12/2012 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Volt | 01/2015-12/2015 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Volt | 01/2016-12/2018 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chrysler | 200 | 01/2014-12/2016 | 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Chrysler | 200 | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Chrysler | 200 | 01/2017-12/2017 | 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Chrysler | 200 | 01/2012-12/2013 | 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Chrysler | 200 | 01/2008-12/2014 | 315MHz | | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Chrysler | 300 | 01/2016-12/2016 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300 | 01/2017-12/2017 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300 | 01/2018-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|---------------------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Chrysler | 300 | 01/2014-12/2015 | 433MHz | LX | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300 | 01/2006-12/2007 | 433MHz | LX | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Chrysler | 300 | 01/2005-12/2006 | 315MHz | LX | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Chrysler | 300 | 01/2008-12/2008 | 433MHz | LX | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Chrysler | 300 | 01/2007-12/2007 | 315MHz | LX | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Chrysler | 300 | 01/2011-12/2013 | 433MHz | LX | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300 | 01/2010-12/2010 | 433MHz | LX | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300 | 01/2009-12/2009 | 433MHz | LX | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300 SRT | 01/2018-12/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300 SRT | 01/2013-12/2017 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300 SRT | 01/2010-12/2012 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300C | 01/2014-12/2015 | 433MHz 56029400AE | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300C | 06/2005-05/2009 | 433MHz | LE48 | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Chrysler | 300C | 01/2006-12/2006 | 315MHz | | ● | ● | ● | O | 315MHz | Continental | ● | ● |
| Chrysler | 300C | 01/2016-12/2017 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300C | 01/2018-12/2018 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300M | 01/2002-12/2004 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chrysler | Aspen | 01/2012-12/2015 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Chrysler | Aspen | 01/2007-12/2007 | 315MHz | HG | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Chrysler | Aspen | 01/2008-12/2011 | 315MHz | HG | ● | ● | ● | O/A | 315MHz | Schrader | ● | ● |
| Chrysler | Concorde | 01/2002-12/2004 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chrysler | Crossfire | 01/2003-12/2008 | 433MHz | ZH | ● | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Chrysler | Crossfire | 01/2005-12/2006 | 315MHz | ZH | ● | ● | ○ | C | 315MHz | Continental | ● | ● |
| Chrysler | Crossfire | 01/2009-12/2011 | 315MHz | ZH | ● | ● | ○ | O | 315MHz | Continental | ● | ● |
| Chrysler | Crossfire | 01/2009-12/2011 | 433MHz | ZH | ● | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Chrysler | Crossfire (International) | 01/2007-12/2008 | 433MHz | ZH | ● | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Chrysler | Crossfire (International) | 01/2007-12/2008 | 315MHz | ZH | ● | ● | ○ | C | 315MHz | Continental | ● | ● |
| Chrysler | Crossfire (NAFTA) | 01/2007-12/2008 | 433MHz | ZH | ● | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Chrysler | Crossfire (NAFTA) | 01/2007-12/2008 | 315MHz | ZH | ● | ● | ○ | C | 315MHz | Continental | ● | ● |
| Chrysler | Intrepid | 01/2002-12/2004 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chrysler | PT Cruiser | 11/2007-12/2010 | 315MHz | PT | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Chrysler | Pacifica | 01/2003-12/2003 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Chrysler | Pacifica | 01/2004-12/2005 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Chrysler | Pacifica | 01/2004-12/2005 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chrysler | Pacifica | 01/2006-12/2008 | 315MHz | CS | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Chrysler | Pacifica | 01/2017-12/2017 | 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Chrysler | Pacifica | 01/2018-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Chrysler | Prowler | 01/2001-12/2002 | 433MHz | | ● | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Chrysler | Sebring | 01/2007-12/2010 | 433MHz | JS | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Chrysler | Sebring | 01/2008-12/2011 | 315MHz | JS | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Chrysler | Sebring | 01/2007-12/2007 | 315MHz | JS | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Chrysler | Town & Country | 01/2011-12/2013 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | Town & Country | 01/2006-12/2010 | 315MHz | | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Chrysler | Town & Country | 01/2007-12/2010 | 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|----------------|-----------------|------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Chrysler | Town & Country | 01/2014-12/2015 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | Town & Country | 01/2002-12/2003 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chrysler | Town & Country | 01/2004-12/2005 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Chrysler | Town & Country | 01/2016-12/2017 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | Town & Country | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | Voyager | 01/2002-12/2003 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chrysler | Voyager | 01/2017-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| DFM | MX6 | 01/2015-12/2016 | QY1036 433MHz | | ○ | ● | ○ | C | 433MHz | Baolong | ● | ● |
| DFM | ix5 | 01/2018-12/2021 | 433MHz | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| DFM | ix7 | 11/2019-12/2020 | 433MHz | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Dodge | Attitude | 01/2015-12/2019 | 315MHz | | ○ | ● | ○ | C | 315MHz | Continental | ● | ● |
| Dodge | Avenger | 01/2007-12/2010 | 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Dodge | Avenger | 01/2007-12/2016 | 315MHz | | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Dodge | C/V | 01/2015-12/2016 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Dodge | C/V | 01/2012-12/2012 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Dodge | C/V | 01/2013-12/2014 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Dodge | Caliber | 01/2007-12/2012 | 433MHz | | ● | ● | ● | O | 433MHz | Schrader | ● | ● |
| Dodge | Caliber | 01/2007-12/2007 | 315MHz | PM | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Dodge | Caliber | 01/2008-12/2009 | 315MHz | PM | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Dodge | Caliber | 01/2010-12/2010 | 315MHz | PM | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Dodge | Caliber | 01/2011-12/2012 | 315MHz | PM | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Dodge | Caravan | 01/2002-12/2003 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Dodge | Caravan | 01/2004-12/2005 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Dodge | Caravan | 01/2006-06/2010 | 315MHz | | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Dodge | Challenger | 01/2010-12/2010 | 433MHz | LC | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Challenger | 01/2009-12/2009 | 433MHz | LC | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Challenger | 01/2008-12/2008 | 433MHz | LC | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Challenger | 01/2019-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Challenger | 01/2018-12/2018 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Challenger | 01/2017-12/2017 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Challenger | 01/2016-12/2016 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Challenger | 01/2014-12/2015 | 433MHz | LC | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Challenger | 01/2011-12/2013 | 433MHz | LC | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Challenger SRT | 01/2018-12/2021 | 433MHz | LD | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Challenger SRT | 01/2015-12/2017 | 433MHz | LD | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Charger | 01/2018-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Charger | 08/2017-12/2017 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Charger | 01/2017-07/2017 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Charger | 01/2009-12/2009 | 433MHz | LX | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Charger | 01/2007-12/2007 | 315MHz | LX | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Dodge | Charger | 01/2008-12/2008 | 433MHz | LX | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Dodge | Charger | 01/2016-12/2016 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Charger | 01/2014-12/2015 | 433MHz | LD | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Charger | 01/2011-12/2013 | 433MHz | LD | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Charger | 01/2010-12/2010 | 433MHz | LX | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|---------------|-----------------|-----------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Dodge | Charger | 01/2005-12/2006 | 315MHz | LX | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Dodge | Charger SRT | 01/2018-06/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Charger SRT | 01/2016-12/2017 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Charger SRT | 01/2010-12/2010 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Charger SRT | 01/2009-12/2009 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Dakota | 01/2011-12/2011 | 315MHz | ND | ● | ● | ● | O/A | 315MHz | Schrader | ● | ● |
| Dodge | Dakota | 01/2008-12/2010 | Snap in 315MHz | ND | ● | ● | ● | O/A | 315MHz | Schrader | ● | ● |
| Dodge | Dakota | 01/2008-12/2010 | Clamp in 315MHz | ND | ● | ● | ● | O/A | 315MHz | Schrader | ● | ● |
| Dodge | Dart | 10/2012-12/2019 | 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Dodge | Durango | 01/2018-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Dodge | Durango | 01/2016-12/2017 | 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Dodge | Durango | 01/2009-12/2010 | 315MHz | HB | ● | ● | ● | O/A | 315MHz | Schrader | ● | ● |
| Dodge | Durango | 01/2007-12/2008 | 315MHz | HB | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Dodge | Durango | 01/2014-12/2016 | 433MHz | WD | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Durango | 01/2011-12/2013 | 433MHz | WD | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Durango SRT | 01/2018-12/2022 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Dodge | Grand Caravan | 01/2001-12/2003 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Dodge | Grand Caravan | 01/2018-12/2022 | SCH 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Grand Caravan | 01/2017-12/2017 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Grand Caravan | 01/2016-12/2016 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Grand Caravan | 01/2014-12/2015 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Grand Caravan | 01/2011-12/2013 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Grand Caravan | 01/2008-12/2010 | 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Dodge | Grand Caravan | 01/2006-12/2007 | 315MHz | | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Dodge | Grand Caravan | 01/2004-12/2005 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Dodge | Intrepid | 01/2002-12/2004 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Dodge | Journey | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Journey | 11/2017-12/2017 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Journey | 10/2016-10/2017 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Journey | 01/2014-09/2016 | 433MHz | JC | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Journey | 01/2011-12/2013 | 433MHz | JC | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Journey | 01/2010-12/2010 | Hi line 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Journey | 01/2010-12/2010 | Lo Line 433MHz | JC | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Dodge | Journey | 01/2009-12/2009 | 433MHz | JC | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Dodge | Magnum | 01/2011-12/2011 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Magnum | 01/2010-12/2010 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Magnum | 01/2009-12/2009 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Magnum | 01/2008-12/2008 | 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Dodge | Magnum | 01/2007-12/2007 | 315MHz | | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Dodge | Magnum | 01/2005-12/2006 | 315MHz | | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Dodge | Nitro | 01/2009-12/2012 | 315MHz | KA | ● | ● | ● | O/A | 315MHz | Schrader | ● | ● |
| Dodge | Nitro | 11/2006-12/2008 | 315MHz | KA | ● | ● | ● | O/A | 315MHz | Schrader | ● | ● |
| Dodge | Nitro | 06/2006-12/2012 | 433MHz | KA | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|--------------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Dodge | Ram 1500 | 01/2019-12/2022 | DT 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Ram 1500 | 01/2018-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | TRW | ● | ● |
| Dodge | Ram 2500 PICKUP | 01/2019-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | TRW | ● | ● |
| Dodge | Ram 2500/3500 | 01/2018-12/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | TRW | ● | ● |
| Dodge | Ram 3500 DRW | 01/2018-12/2022 | 433MHz Alloy wheel | | ○ | ● | ○ | A | 433MHz | TRW | ● | ● |
| Dodge | Ram 3500 DRW | 01/2018-12/2022 | 433MHz Steel wheel | | ○ | ● | ○ | A | 433MHz | TRW | ● | ● |
| Dodge | Ram 3500 DRW Alloy | 01/2019-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | TRW | ● | ● |
| Dodge | Ram 3500 PICKUP | 01/2019-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | TRW | ● | ● |
| Dodge | Ram 4500/5500 | 01/2018-12/2018 | 433MHz | | ● | ● | ○ | O/A | 433MHz | TRW | ● | ● |
| Dodge | Ram 4500/5500 DRW | 01/2019-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | TRW | ● | ● |
| Dodge | Ram Cargo | 01/2015-12/2015 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Ram Power Wagon | 01/2018-06/2019 | 433MHz | | ● | ● | ○ | O | 433MHz | TRW | ● | ● |
| Dodge | Ram Power Wagon | 01/2017-12/2017 | 433MHz | | ● | ● | ● | O | 433MHz | TRW | ● | ● |
| Dodge | Ram ProMaster City | 01/2015-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Ram Promaster | 01/2018-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Ram Promaster | 01/2014-12/2017 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Ram Promaster City | 01/2018-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Ram Promaster City | 01/2015-12/2017 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Ram Rebel | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | O | 433MHz | TRW | ● | ● |
| Dodge | Ram Rebel | 01/2016-12/2017 | 433MHz | | ● | ● | ● | O | 433MHz | TRW | ● | ● |
| Dodge | Ram Series | 10/2015-12/2017 | DRW 433MHz | | ● | ● | ● | O/A | 433MHz | TRW | ● | ● |
| Dodge | Ram Series | 10/2013-12/2017 | 433MHz | | ● | ● | ● | O/A | 433MHz | TRW | ● | ● |
| Dodge | Ram Series | 01/2018-12/2018 | DRW 433MHz | | ● | ● | ○ | O/A | 433MHz | TRW | ● | ● |
| Dodge | Ram Series | 01/2010-12/2014 | SCH New 433MHz | D2 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Ram Series | 01/2007-12/2009 | 315MHz | | ● | ● | ● | O/A | 315MHz | Schrader | ● | ● |
| Dodge | Ram Series | 01/2009-12/2010 | SCH Old 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Ram Series DRW | 01/2014-12/2017 | 433MHz Steel wheel | | ● | ● | ○ | O/A | 433MHz | TRW | ● | ● |
| Dodge | Ram Series DRW | 01/2014-12/2017 | 433MHz Alloy wheel | | ● | ● | ○ | O/A | 433MHz | TRW | ● | ● |
| Dodge | SRT Viper | 01/2016-12/2017 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Sprinter | 01/2007-12/2020 | 315MHz | VB | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Dodge | Stratus | 01/2007-12/2007 | 315MHz | JR | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Dodge | Viper | 01/2003-12/2011 | 433MHz | ZB | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Dodge | viper | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Dodge | viper | 01/2017-12/2017 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | viper | 01/2013-12/2016 | 433MHz | VX | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| FAW | BESTURN T33 | 08/2019-12/2020 | Baolong 433MHz | | ● | ● | ○ | O | 433MHz | Baolong | ● | ● |
| FAW | BESTURN T77 | 01/2017-12/2017 | Baolong 433MHz | | ● | ● | ○ | O | 433MHz | Baolong | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|----------------|-----------------|------------------|---------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Ferrari | 458 Italia | 01/2014-12/2016 | 433MHz | F142 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 458 Italia | 01/2009-12/2013 | 433MHz | F142 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 458 Speciale | 01/2013-12/2016 | 433MHz | F142 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 458 Spider | 01/2009-12/2020 | 433MHz | F142 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 488 | 01/2015-12/2021 | 433MHz | F142 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 550 Maranello | 01/2010-12/2012 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 550 Maranello | 01/1998-12/2002 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 575M Maranello | 01/2002-12/2006 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Ferrari | 575M Maranello | 01/2002-12/2006 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 599 GTB | 01/2004-12/2014 | 433MHz | F141 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 599 GTO | 01/2004-12/2012 | 433MHz | F141 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 599 SA Aperta | 01/2004-12/2012 | 433MHz | F141 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 612 Scaglietti | 01/2004-12/2012 | 433MHz | F137 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 812 Superfast | 01/2016-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Ferrari | California | 01/2015-06/2019 | 433MHz | F149 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | California | 01/2008-12/2014 | 433MHz | F149 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | Enzo | 01/2002-12/2009 | 433MHz | F140 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F12 Berlinetta | 10/2012-12/2014 | 315MHz | F151/ F152 | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Ferrari | F12 Berlinetta | 10/2012-12/2022 | 433MHz 282189 | F151/ F152 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F12 tdf | 01/2015-12/2021 | 433MHz | F151/ F152 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F430 | 01/2004-12/2007 | 433MHz | F131E | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F430 | 01/2008-12/2011 | 433MHz | F131E | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F488 | 01/2021-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F588 Dino | 01/2019-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F8 Tributo | 01/2019-12/2022 | 433MHz | F151/ F152 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | FF | 01/2011-06/2019 | 315MHz | F151 | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Ferrari | FF | 01/2011-06/2019 | 433MHz | F151 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | FXX | 01/2003-12/2009 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | GTC4 Lusso | 01/2016-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | La Ferrari | 01/2014-12/2019 | 433MHz | F150 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | La Ferrari | 01/2013-12/2020 | 315MHz | F150 | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Ferrari | Portofino | 01/2016-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Ferrari | Roma | 01/2020-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | SF90 Stralade | 01/2020-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | Spider | 01/2002-12/2009 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Fiat | 124 Spider | 01/2016-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Fiat | 124 Spider | 08/2015-12/2021 | 433MHz | NF/J12F | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Fiat | 500 | 01/2011-12/2013 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Fiat | 500 | 01/2017-12/2022 | 433MHz | | ● | ● | ● | O | 433MHz | Schrader | ● | ● |
| Fiat | 500 | 01/2014-12/2016 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Fiat | 500C | 01/2015-12/2017 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Fiat | 500E | 01/2015-12/2017 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Fiat | 500L | 01/2017-12/2022 | 433MHz | | ● | ● | ● | O | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|-----------------|-----------------|-------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Fiat | 500L | 03/2013-12/2016 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Fiat | 500X | 01/2022-12/2022 | 433MHz | | ○ | ● | ● | A | 433MHz | Schrader | ● | ● |
| Fiat | 500X | 01/2017-12/2021 | 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Fiat | 500X | 01/2014-12/2016 | 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Fiat | Ducato | 06/2014-06/2024 | 433MHz | X2/50 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Ford | Bronco | 01/2021-12/2022 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Bronco | 01/2020-12/2020 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Bronco Sport | 01/2021-12/2022 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | C-Max | 01/2017-12/2020 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | C-Max | 01/2014-12/2016 | 315MHz | C344N | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | C-Max | 01/2013-12/2013 | 315MHz | C344N | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | C-Max | 01/2012-12/2012 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Crown Victoria | 01/2006-12/2007 | 315MHz | | ● | ● | ○ | S | 315MHz | Continental | ● | ● |
| Ford | Crown Victoria | 01/2009-12/2011 | 315MHz | | ● | ● | ○ | S | 315MHz | Continental | ● | ● |
| Ford | Crown Victoria | 01/2008-12/2008 | 315MHz | | ● | ● | ○ | S | 315MHz | Continental | ● | ● |
| Ford | E-Series | 01/2008-12/2009 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Lear | ● | ● |
| Ford | E-Series | 01/2018-12/2020 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | E-Series | 01/2010-12/2017 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | E-Series | 01/2009-12/2010 | Band 315MHz | | ● | ● | ● | O/S | 315MHz | Lear | ● | ● |
| Ford | E-Series | 01/2007-12/2007 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Lear | ● | ● |
| Ford | E-Series SD | 01/2021-12/2022 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | E-Series SD DRW | 01/2021-12/2022 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Ecosport | 07/2017-12/2021 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Ford | Ecosport | 06/2015-06/2017 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Edge | 01/2012-12/2012 | 315MHz | U387 | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Edge | 01/2013-12/2014 | 315MHz | U387 | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Edge | 01/2013-12/2015 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | Edge | 01/2015-12/2022 | 315MHz | CD539N | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | Edge | 01/2018-12/2019 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | Edge | 01/2007-12/2010 | no Chrome rims 315MHz | U387 | ● | ● | ● | O/S | 315MHz | Continental | ● | ● |
| Ford | Edge | 01/2007-12/2007 | with Chrome rims 315MHz | U387 | ● | ● | ● | O/S | 315MHz | Continental | ● | ● |
| Ford | Edge | 01/2011-12/2011 | 315MHz | U387 | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Escape | 01/2011-12/2011 | 315MHz | U377 | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | Escape | 01/2010-12/2010 | 315MHz | U377 | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Escape | 01/2009-12/2009 | 315MHz | U377 | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | Escape | 01/2008-12/2008 | 315MHz | U377 | ● | ● | ● | O/S | 315MHz | Continental | ● | ● |
| Ford | Escape | 01/2006-12/2007 | 315MHz | U204 | ● | ● | ○ | S | 315MHz | Continental | ● | ● |
| Ford | Escape | 01/2005-12/2005 | 315MHz | U204 | ○ | ● | ○ | S | 315MHz | Continental | ● | ● |
| Ford | Escape | 01/2012-12/2012 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | Escape | 01/2012-12/2012 | 315MHz | U377 | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | Escape | 01/2013-09/2013 | 315MHz | C520 | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Escape | 01/2013-12/2013 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Ford | Escape | 10/2013-12/2014 | 315MHz | C520 | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | Escape | 01/2014-12/2016 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | Escape | 01/2015-12/2015 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|----------------|-----------------|-------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Ford | Escape | 01/2016-12/2017 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Escape | 01/2020-12/2022 | 315MHz | | ● | ● | ● | A/S | 315MHz | Schrader | ● | ● |
| Ford | Escape | 01/2020-12/2022 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Escape | 01/2017-12/2019 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Escape | 01/2018-12/2019 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Exp Sport Trac | 01/2008-12/2010 | 315MHz | | ● | ● | ○ | S | 315MHz | Continental | ● | ● |
| Ford | Exp Sport Trac | 01/2006-12/2007 | 315MHz | | ● | ● | ○ | S | 315MHz | Continental | ● | ● |
| Ford | Expedition | 01/2016-12/2017 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Ford | Expedition | 01/2016-12/2016 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Expedition | 01/2015-12/2015 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Expedition | 01/2015-12/2015 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Ford | Expedition | 01/2013-12/2014 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Expedition | 01/2011-12/2014 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Expedition | 01/2007-12/2010 | with Chrome rims 315MHz | | ● | ● | ● | 0/S | 315MHz | Continental | ● | ● |
| Ford | Expedition | 01/2007-12/2010 | no Chrome rims 315MHz | | ● | ● | ● | 0/S | 315MHz | Continental | ● | ● |
| Ford | Expedition | 01/2005-12/2006 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Expedition | 01/2004-12/2004 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Expedition | 01/2003-12/2003 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Expedition | 01/2018-12/2022 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Expedition | 01/2017-12/2017 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Explorer | 01/2011-12/2011 | 315MHz | U502 | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Explorer | 01/2008-12/2010 | 315MHz | | ● | ● | ○ | S | 315MHz | Continental | ● | ● |
| Ford | Explorer | 01/2006-12/2007 | 315MHz | | ● | ● | ○ | S | 315MHz | Continental | ● | ● |
| Ford | Explorer | 01/2005-12/2005 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Explorer | 01/2002-12/2002 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Explorer | 01/2003-12/2003 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Explorer | 01/2004-12/2004 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Explorer | 01/2020-12/2022 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Explorer | 01/2011-12/2012 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Ford | Explorer | 01/2012-12/2012 | 315MHz | U502 | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Explorer | 01/2013-05/2015 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Ford | Explorer | 01/2013-09/2015 | 315MHz | U502 | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Explorer | 06/2015-12/2019 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Explorer | 10/2015-12/2017 | 315MHz | U502 | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Explorer | 01/2018-12/2019 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Explorer | 01/2020-12/2021 | 315MHz | | ○ | ● | ○ | A/S | 315MHz | Schrader | ● | ● |
| Ford | F-150 | 01/2018-12/2020 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | F-150 | 01/2015-12/2018 | 433MHz | P415 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Ford | F-150 | 01/2015-12/2017 | 315MHz | P552 | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | F-150 | 01/2013-12/2014 | 433MHz | P415 | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Ford | F-150 | 01/2012-12/2014 | 315MHz | P415 | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | F-150 | 01/2011-12/2011 | 315MHz | P415 | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | F-150 | 01/2009-12/2010 | 315MHz | P415 | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | F-150 | 01/2006-12/2008 | 315MHz | P221 | ● | ● | ○ | S | 315MHz | Continental | ● | ● |
| Ford | F-150 | 01/2021-12/2022 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|-----------------|-----------------|----------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Ford | F-150 HD | 01/2015-12/2015 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | F-150 HD | 01/2008-12/2010 | 315MHz | | ● | ● | ● | O/S | 315MHz | Lear | ● | ● |
| Ford | F-150 HD | 01/2011-12/2014 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | F-Series | 01/2017-12/2020 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | F-Series | 01/2015-12/2016 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | F-Series | 01/2009-12/2014 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | F-Series | 01/2006-12/2008 | 315MHz | | ● | ● | ○ | S | 315MHz | Continental | ● | ● |
| Ford | F-Series SD | 01/2017-12/2017 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | F-Series SD | 01/2017-12/2019 | Trailer 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | F-Series SD | 01/2018-12/2022 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | F-Series SD | 01/2015-12/2018 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | F-Series SD | 01/2011-12/2016 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | F-Series SD | 06/2010-12/2010 | Snap in 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | F-Series SD | 01/2009-05/2010 | Banded 315MHz | | ● | ● | ● | O/S | 315MHz | Lear | ● | ● |
| Ford | F-Series SD | 01/2007-12/2008 | Banded 315MHz | | ● | ● | ○ | S | 315MHz | Lear | ● | ● |
| Ford | F-Series SD DRW | 01/2018-12/2021 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | F-Series SD DRW | 01/2018-12/2019 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | F-Series SD DRW | 01/2016-12/2017 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | F-series | 01/2021-12/2022 | 315MHz | | ○ | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Ford | Fiesta | 01/2018-12/2020 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Fiesta | 01/2014-12/2017 | 315MHz | B299N | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Fiesta | 01/2011-12/2013 | 315MHz | B299N | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Ford | Fiesta ST | 01/2018-12/2019 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Five Hundred | 01/2006-12/2007 | 315MHz | D258 | ○ | ● | ○ | S | 315MHz | Continental | ● | ● |
| Ford | Flex | 01/2016-12/2019 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Flex | 01/2009-12/2010 | 315MHz | D471 | ● | ● | ● | O/S | 315MHz | Continental | ● | ● |
| Ford | Flex | 01/2016-12/2019 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Ford | Flex | 01/2013-12/2020 | 315MHz | D471 | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Flex | 01/2013-12/2015 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Ford | Flex | 01/2012-12/2012 | 315MHz | D471 | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | Flex | 01/2011-12/2011 | 315MHz | D471 | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | Focus | 01/2007-12/2007 | 315MHz | C170 | ○ | ● | ○ | S | 315MHz | Continental | ● | ● |
| Ford | Focus | 01/2015-12/2020 | 315MHz | C346N | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | Focus | 01/2014-12/2014 | 315MHz | C346N | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | Focus | 01/2013-12/2013 | 315MHz | C346N | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Focus | 01/2012-12/2012 | 315MHz | C170 | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Focus | 01/2010-12/2011 | 315MHz | C170 | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | Focus | 01/2008-12/2009 | 315MHz | C170 | ● | ● | ● | O/S | 315MHz | Continental | ● | ● |
| Ford | Focus RS | 01/2018-12/2018 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Focus RS | 01/2016-12/2017 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | Focus ST | 01/2018-12/2018 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Freestar | 01/2006-12/2007 | 315MHz | V229 | ● | ● | ○ | S | 315MHz | Continental | ● | ● |
| Ford | Freestar | 01/2005-12/2005 | 315MHz | V229 | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|-------------------------|-----------------|----------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Ford | Freestar | 01/2004-12/2004 | 315MHz | V229 | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Freestyle | 01/2005-12/2007 | 315MHz | | ○ | ● | ○ | S | 315MHz | Continental | ● | ● |
| Ford | Fusion | 01/2006-12/2007 | 315MHz | CD338 | ● | ● | ○ | S | 315MHz | Continental | ● | ● |
| Ford | Fusion | 01/2018-12/2021 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Fusion | 01/2017-12/2019 | 433MHz | CD389 | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Fusion | 01/2017-12/2017 | 315MHz | CD539N | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Fusion | 07/2013-12/2016 | 315MHz | CD391 | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Fusion | 01/2013-12/2015 | 433MHz | CD391 | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Fusion | 07/2012-06/2013 | 315MHz | CD391 | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Fusion | 01/2010-06/2012 | 315MHz | CD338 | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Fusion | 01/2008-12/2009 | 315MHz | CD338 | ● | ● | ○ | S | 315MHz | Continental | ● | ● |
| Ford | GT | 01/2017-12/2021 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Grand Marquis | 01/2007-12/2011 | 315MHz | | ○ | ● | ○ | S | 315MHz | Continental | ● | ● |
| Ford | Interceptor Crown Vic | 01/2006-12/2014 | 315MHz | | ○ | ● | ○ | S | 315MHz | Continental | ● | ● |
| Ford | Interceptor Explorer | 01/2015-08/2015 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Interceptor Explorer | 09/2015-12/2019 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Interceptor Explorer | 01/2011-12/2014 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Interceptor Taurus | 01/2011-12/2019 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Kuga | 01/2014-12/2019 | 433MHz | C520 | ● | ● | ● | 0/S/A | 433MHz | Schrader | ● | ● |
| Ford | Mach E | 01/2020-12/2022 | 315MHz | | ○ | ● | ○ | A/S | 315MHz | Schrader | ● | ● |
| Ford | Maverick | 01/2022-12/2022 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Mustang | 07/2006-12/2009 | 315MHz | | ● | ● | ○ | S | 315MHz | Continental | ● | ● |
| Ford | Mustang | 01/2005-06/2006 | 315MHz | | ○ | ● | ○ | S | 315MHz | Continental | ● | ● |
| Ford | Mustang | 01/2010-12/2011 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Mustang | 01/2012-09/2014 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Mustang | 01/2013-09/2014 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Mustang | 10/2014-12/2017 | 315MHz | S550 | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Mustang | 10/2014-12/2018 | 433MHz | S550 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Mustang | 01/2018-12/2022 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Mustang Mach-E | 01/2021-12/2022 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | PUMA | 01/2020-12/2020 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | PUMA | 11/2019-12/2021 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Police Responder Hybrid | 01/2019-12/2020 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Ranger | 01/2008-12/2011 | 315MHz | | ● | ● | ○ | S | 315MHz | Continental | ● | ● |
| Ford | Ranger | 01/2006-12/2007 | 315MHz | J97 | ● | ● | ○ | S | 315MHz | Continental | ● | ● |
| Ford | Ranger | 01/2022-12/2022 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Ranger | 01/2019-12/2021 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Ford | Ranger | 01/2019-12/2021 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Ranger | 01/2018-12/2018 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Ranger | 01/2012-12/2017 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | SSV Plug-In Hybrid | 01/2019-12/2020 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|------------------------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Ford | Shelby GT500 | 01/2015-12/2017 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | Shelby GT500 | 01/2012-12/2014 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Shelby GT500 | 01/2013-12/2015 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Shelby GT500 | 01/2018-12/2021 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | Special Service Police Sedan | 01/2014-12/2017 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Taurus | 01/2013-10/2015 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Ford | Taurus | 01/2017-12/2017 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Taurus | 01/2018-12/2021 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Taurus | 01/2016-12/2016 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | Taurus | 11/2015-12/2019 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | Taurus | 11/2012-12/2015 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Taurus | 01/2012-10/2012 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | Taurus | 01/2011-12/2011 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | Taurus | 05/2010-12/2010 | Snap in 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | Taurus | 01/2008-04/2010 | Banded 315MHz | | ● | ● | ● | O/S | 315MHz | Continental | ● | ● |
| Ford | Taurus X | 01/2008-12/2009 | 315MHz | | ● | ● | ● | O/S | 315MHz | Continental | ● | ● |
| Ford | Transit | 01/2015-12/2015 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Ford | Transit | 01/2014-12/2014 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Transit | 01/2010-12/2014 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Transit | 01/2021-12/2022 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Transit | 01/2017-12/2020 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Ford | Transit | 01/2016-12/2016 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Ford | Transit Cargo & Wagon | 01/2020-12/2020 | 315MHz | | ○ | ● | ○ | A/S | 315MHz | Schrader | ● | ● |
| Ford | Transit Connect | 01/2019-12/2020 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | Transit Connect | 01/2018-12/2018 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | Transit Connect | 01/2014-12/2017 | 315MHz | V408N | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | Transit Connect | 01/2021-12/2022 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Transit Connect | 01/2010-12/2011 | 315MHz | V227N | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Ford | Transit Connect | 01/2012-12/2012 | 315MHz | V227N | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Ford | Transit Connect | 01/2013-12/2013 | 315MHz | V408N | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Ford | Transit DRW | 01/2020-12/2020 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Transit LCV | 01/2014-12/2019 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Windstar | 01/2001-12/2003 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| GMC | Acadia | 01/2013-12/2013 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Acadia | 01/2012-12/2013 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| GMC | Acadia | 11/2008-12/2011 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| GMC | Acadia | 01/2007-10/2008 | 315MHz | | ○ | ● | ○ | S | 315MHz | Continental | ● | ● |
| GMC | Acadia | 09/2018-12/2022 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Acadia | 09/2018-12/2019 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| GMC | Acadia | 11/2016-08/2018 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Acadia | 11/2016-08/2018 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| GMC | Acadia | 01/2016-10/2016 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Acadia | 06/2014-10/2016 | 315MHz 23445327 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|--------|-----------------|------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| GMC | Acadia | 01/2014-10/2016 | 315MHz 25920615 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Acadia | 01/2014-12/2015 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Canyon | 01/2010-06/2013 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| GMC | Canyon | 01/2007-12/2009 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| GMC | Canyon | 01/2014-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Canyon | 01/2017-12/2020 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Canyon | 01/2020-12/2022 | 315MHz 13512346 | | ● | ● | ● | 0 | 315MHz | Schrader | ● | ● |
| GMC | Denali | 06/2020-06/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| GMC | Envoy | 01/2007-12/2009 | SCH Snap in 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| GMC | Envoy | 01/2007-12/2007 | TRW Clamp in 315MHz | | ● | ● | ● | S | 315MHz | TRW | ● | ● |
| GMC | Envoy | 01/2006-12/2009 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| GMC | Envoy | 01/2006-12/2006 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| GMC | Envoy | 01/2005-12/2005 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| GMC | Envoy | 01/2007-12/2009 | SCH Clamp in 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| GMC | Hummer | 01/2022-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| GMC | Savana | 01/2009-12/2013 | Clamp in 315MHz | | ● | ● | ● | 0/S | 315MHz | Continental | ● | ● |
| GMC | Savana | 01/2019-12/2021 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| GMC | Savana | 01/2014-12/2015 | Snap in 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Savana | 01/2008-12/2008 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Continental | ● | ● |
| GMC | Savana | 01/2009-12/2013 | Snap in 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Savana | 01/2014-12/2015 | Clamp in 315MHz | | ● | ● | ● | 0/S | 315MHz | Continental | ● | ● |
| GMC | Savana | 01/2016-12/2016 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Savana | 01/2016-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Savana | 01/2017-12/2018 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| GMC | Savana | 01/2017-12/2020 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2017-12/2021 | 315MHz | XL7 | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2018-12/2022 | 433MHz 13516165 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2021-12/2021 | 433MHz 13530661 | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2015-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2009-12/2013 | Snap in 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2010-12/2011 | Clamp in 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2007-12/2008 | SCH Snap in 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2007-12/2007 | SCH Clamp in 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2014-12/2014 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2016-12/2018 | 433MHz 13598773 | XL8 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|----------------|-----------------|---------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| GMC | Sierra | 01/2007-12/2007 | TRW Clamp in 315MHz | | ● | ● | ● | 0/S | 315MHz | TRW | ● | ● |
| GMC | Sierra | 01/2005-12/2006 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2004-12/2004 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| GMC | Sierra Classic | 01/2007-12/2007 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| GMC | Sierra DRW | 01/2015-12/2016 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| GMC | Sierra DRW | 01/2017-12/2019 | 433MHz | XL8 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| GMC | Sierra DRW | 01/2017-12/2019 | 315MHz | XL7 | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| GMC | Sierra Trailer | 01/2019-12/2020 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| GMC | Terrain | 01/2017-12/2017 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| GMC | Terrain | 01/2017-12/2017 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| GMC | Terrain | 01/2010-12/2011 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Terrain | 01/2018-12/2022 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| GMC | Terrain | 01/2015-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Terrain | 01/2018-12/2020 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| GMC | Terrain | 01/2015-12/2016 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Terrain | 01/2015-12/2017 | 315MHz 13586335 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Terrain | 01/2010-12/2012 | 315Mhz 20925924 | | ○ | ● | ○ | C | 315MHz | Schrader | ● | ● |
| GMC | Terrain | 01/2012-12/2014 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Terrain | 01/2012-12/2014 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Yukon | 01/2021-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| GMC | Yukon All | 01/2004-07/2004 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| GMC | Yukon All | 01/2021-12/2021 | 433MHz 13530661 | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| GMC | Yukon All | 01/2018-12/2021 | 433MHz 13516165 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Yukon All | 01/2017-12/2020 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Yukon All | 01/2016-12/2018 | 433MHz 13598773 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Yukon All | 03/2014-12/2016 | 315MHz 13598772 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Yukon All | 01/2014-12/2014 | 315MHz 25920615 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Yukon All | 01/2010-12/2011 | Clamp in 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Yukon All | 01/2009-12/2013 | Snap in 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Yukon All | 01/2008-12/2008 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Yukon All | 01/2007-12/2007 | Clamp in 315MHz | | ● | ● | ● | 0/S | 315MHz | TRW | ● | ● |
| GMC | Yukon All | 01/2007-12/2007 | Snap in 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Yukon All | 08/2004-12/2006 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Geely | Atlas | 09/2019-12/2020 | SCH 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | FY11 | 07/2021-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| HaiMa | Haima 7 | 01/2012-12/2013 | 433MHz | | ○ | ● | ○ | S | 433MHz | Steel Mate | ● | ● |
| HaiMa | M3 | 01/2016-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TTE | ● | ● |
| HaiMa | S5 | 01/2014-06/2020 | 433MHz | | ● | ● | ○ | C | 433MHz | Steel Mate | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|----------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| HanTeng | X5 | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| HanTeng | X7 | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | Dargo | 09/2020-12/2021 | SCH 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Haval | Dargo | 09/2020-12/2021 | SAT 433MHz | | ● | ● | ○ | 0/A | 433MHz | SAT | ● | ● |
| Haval | F7 | 01/2021-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Dias | ● | ● |
| Haval | Jolion | 01/2021-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Dias | ● | ● |
| Honda | Accord | 01/2014-12/2019 | Direct 433MHz | 2GA/2GB/QE | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | Accord | 01/2013-12/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Honda | Accord | 01/2008-12/2012 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Honda | CR-V | 01/2007-12/2011 | Alloy/Steel 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Honda | CR-V | 01/2012-12/2014 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Honda | CR-V | 01/2014-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Honda | CR-V | 01/2015-12/2021 | Direct 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | CR-Z | 01/2016-12/2016 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | CR-Z | 01/2011-12/2017 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Civic | 01/2014-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Honda | Civic | 01/2012-12/2014 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Civic | 06/2005-12/2011 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Clarity | 01/2016-12/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Honda | Crosstour | 01/2010-12/2015 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Honda | Element | 01/2008-12/2008 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Element | 01/2009-12/2011 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Element | 01/2006-12/2007 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | FCX Clarity | 01/2010-12/2010 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | Fit | 01/2008-12/2008 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Honda | Fit | 01/2015-12/2017 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Honda | Fit | 01/2018-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Honda | Fit | 01/2009-12/2014 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | GL1800 | 01/2009-12/2015 | MOTOR Cycle 315MHz | | ○ | ○ | ○ | S | 315MHz | LDL Technology | Activate Only | ● |
| Honda | Goldwing | 01/2009-06/2017 | MOTOR Cycle 315MHz | | ○ | ○ | ○ | S | 315MHz | LDL Technology | Activate Only | ● |
| Honda | HR-V | 11/2014-06/2021 | Direct 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | HR-V | 09/2014-12/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | HR-V CROSSOVER | 01/2016-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Honda | Insight | 01/2018-12/2022 | Indirect | | ○ | ○ | ○ | S | | N/A | Indirect | ● |
| Honda | Insight | 05/2009-06/2016 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Legend | 01/2016-12/2017 | Direct 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | Legend | 01/2015-12/2020 | 315MHz | Hybrid | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | NSX | 01/2016-06/2021 | Direct 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | Odyssey | 01/2018-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | Odyssey | 01/2011-12/2020 | 315MHz | EX/EX-L | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Odyssey | 01/2008-12/2010 | 315MHz | EX/EX-L | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|-----------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Honda | Odyssey | 01/2006-12/2007 | 315MHz | EX/EX-L | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Odyssey | 01/2021-12/2022 | A02 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Honda | Odyssey Touring | 01/2018-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | Odyssey Touring | 01/2008-12/2010 | 315MHz | TOUR | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Odyssey Touring | 01/2011-12/2019 | 315MHz | TOUR | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Odyssey Touring | 01/2005-12/2007 | 315MHz | TOUR | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Passport | 01/2019-12/2021 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Honda | Pilot | 01/2018-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | Pilot | 01/2016-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | Pilot | 01/2009-12/2015 | Steel 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Honda | Pilot | 01/2009-12/2015 | Alloy 315MHz | | ● | ● | ○ | 0/A | 315MHz | Pacific | ● | ● |
| Honda | Pilot | 01/2006-12/2008 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Pilot | 01/2005-12/2005 | Alloy 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Pilot | 01/2005-12/2005 | Steel 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Ridgeline | 01/2009-12/2014 | Steel 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Ridgeline | 01/2006-12/2008 | Alloy 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Ridgeline | 01/2006-12/2008 | Steel 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Ridgeline | 01/2009-12/2014 | Alloy 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Ridgeline | 01/2016-12/2019 | Steel 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Ridgeline | 01/2021-12/2022 | 42753T3RA02 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Honda | Ridgeline | 01/2017-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | Ridgeline | 01/2017-12/2019 | Alloy 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | S2000 | 01/2008-12/2009 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Hummer | H2 | 01/2007-12/2007 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Hummer | H2 | 01/2008-12/2008 | 315MHz 15922396 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Hummer | H2 | 01/2008-12/2008 | 315MHz 13598771 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Hummer | H2 | 01/2009-12/2010 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Hummer | H3 | 01/2006-12/2006 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Hummer | H3 | 01/2007-12/2010 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Hummer | H3T | 01/2006-12/2010 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Hyundai | Accent | 04/2011-09/2014 | 433MHz | RB | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Accent | 01/2006-12/2007 | 315MHz | MC | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Accent | 01/2006-03/2011 | 315MHz 529332F000 | MC | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Accent | 04/2011-09/2014 | 315MHz 529332M000 | RB | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Accent | 04/2011-09/2014 | 315MHz 529333N000 | RB | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Accent | 04/2011-12/2021 | Hi Line 433MHz | RB | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Accent | 10/2014-12/2021 | Lo Line 433MHz | RB | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Azera | 01/2006-12/2011 | 315MHz | TG | ● | ● | ○ | 0 | 315MHz | Lear | ● | ● |
| Hyundai | Azera | 01/2012-12/2014 | 315MHz | HG | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Azera | 01/2012-12/2019 | 433MHz | HG | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | Centennial | 01/2013-12/2015 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|-----------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Hyundai | Creta | 01/2021-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Hyundai | Creta | 01/2016-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Elantra | 01/2015-12/2020 | 433MHz | AD | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Elantra | 07/2020-12/2022 | 433MHz 52940L1100 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Elantra | 01/2007-12/2010 | 315MHz | HD | ● | ● | ○ | 0 | 315MHz | Lear | ● | ● |
| Hyundai | Elantra | 01/2021-12/2022 | 433MHz | AD | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Elantra | 10/2013-12/2019 | Lo Line 315MHz | | ● | ● | ○ | 0/A | 315MHz | TRW | ● | ● |
| Hyundai | Elantra | 10/2010-12/2013 | 315MHz | UD/MD | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Elantra GT | 07/2017-12/2019 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Elantra GT | 06/2017-12/2021 | 433MHz | PD | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Elantra GT | 01/2016-06/2017 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Elantra GT | 01/2015-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Elantra GT | 01/2013-12/2015 | 315MHz | GD | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Elantra Touring | 01/2009-12/2012 | 315MHz 529332L500 | FD | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Elantra Touring | 01/2009-12/2012 | 315MHz 529332L700 | FD | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Entourage | 07/2008-12/2010 | 315MHz | EP | ● | ● | ○ | 0 | 315MHz | Huf/Beru | ● | ● |
| Hyundai | Entourage | 10/2006-06/2008 | 315MHz | EP | ● | ● | ○ | 0 | 315MHz | Lear | ● | ● |
| Hyundai | Equus | 03/2013-06/2016 | Hi Line 315MHz | VI | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Equus | 01/2013-12/2016 | 433MHz | VI New | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Equus | 01/2010-07/2013 | 315MHz | VI | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Genesis | 01/2014-12/2017 | 433MHz | DH | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis | 01/2013-12/2016 | 315MHz | BK | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Genesis | 04/2008-12/2012 | 315MHz | BK | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Genesis | 01/2008-12/2014 | TRW 315MHz | BH | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Genesis Coupe | 01/2011-12/2016 | Hi Line 315MHz | BK | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Genesis Coupe | 01/2008-12/2012 | Lo Line 315MHz | BK | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Genesis Coupe | 01/2017-12/2018 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Hyundai | Genesis G70 | 01/2019-12/2021 | 433MHz | IK | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Genesis G70 | 01/2017-12/2018 | 433MHz | IK | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Genesis G80 | 01/2021-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Hyundai | Genesis G80 | 07/2016-12/2022 | 433MHz | DH | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Genesis G90 | 01/2017-12/2022 | 433MHz | HI | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Genesis G90 | 01/2016-12/2016 | 433MHz | HI | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Genesis GV70 | 01/2022-12/2022 | 433MHz | IK | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Hyundai | Genesis GV80 | 01/2021-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Hyundai | Genesis Sedan | 01/2014-06/2016 | 433MHz | DH | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Genesis Sedan | 01/2009-12/2014 | 315MHz | BH | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | H-1 | 01/2013-05/2014 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Ioniq | 01/2016-06/2021 | 433MHz | AE | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Ioniq 5 | 01/2020-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Hyundai | Kona | 01/2017-12/2021 | 433MHz | | ● | ● | ○ | A/O | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|----------------|-----------------|-----------------------|-------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Hyundai | Nexo | 01/2019-12/2022 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Nexo | 04/2018-12/2018 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Palisade | 01/2020-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Palisade | 01/2019-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Santa Cruz | 01/2022-12/2023 | 433MHz 52940L1100 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Santa Cruz | 01/2019-12/2021 | 433MHz 52940L1100 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Santa Fe | 03/2018-12/2022 | 433MHz | TM/TMA | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Santa Fe | 01/2015-12/2019 | 315MHz | NC | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Santa Fe | 01/2017-06/2020 | 433MHz | NC | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Santa Fe | 01/2014-04/2017 | Hi Line 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Santa Fe | 06/2012-12/2014 | 315MHz | NC | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Santa Fe | 10/2009-12/2012 | 315MHz | CM | ● | ● | ○ | 0 | 315MHz | Lear | ● | ● |
| Hyundai | Santa Fe | 01/2008-12/2010 | Lo Line 315MHz | CM | ● | ● | ○ | 0 | 315MHz | Lear | ● | ● |
| Hyundai | Santa Fe | 01/2008-12/2008 | Hi Line 315MHz | CM | ● | ● | ○ | 0 | 315MHz | Huf/Beru | ● | ● |
| Hyundai | Santa Fe | 01/2008-12/2008 | 315MHz | CM | ● | ● | ○ | 0 | 315MHz | Lear | ● | ● |
| Hyundai | Santa Fe | 01/2006-12/2007 | 315MHz | CM | ● | ● | ○ | 0 | 315MHz | Huf/Beru | ● | ● |
| Hyundai | Santa Fe Sport | 01/2018-12/2022 | SCH 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Santa Fe Sport | 01/2013-12/2014 | 315MHz | DMA | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Santa Fe Sport | 01/2018-12/2019 | VDO 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Santa Fe Sport | 01/2015-12/2019 | 315MHz | DMA | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Sonata | 01/2006-12/2008 | 315MHz 529333E000 | NF | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Sonata | 01/2020-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Sonata | 04/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Sonata | 04/2014-12/2019 | Hi Line 433MHz | LF/LFA | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Sonata | 05/2013-12/2016 | Hi Line 315MHz | Hi Line 315MHz | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Sonata | 12/2009-05/2014 | 315MHz 529332M000 | YF | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Sonata | 12/2007-01/2010 | 315MHz 529332F000 | NF | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Sonata Hybrid | 03/2015-12/2019 | Hi Line 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Sonata Hybrid | 01/2011-12/2015 | Lo Line 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Sonata Hybrid | 01/2010-12/2019 | 315MHz | YF HEV | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Staria | 03/2021-12/2027 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Hyundai | Tiburon | 01/2008-12/2008 | Lo Line 315MHz | GK | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Tiburon | 01/2007-12/2007 | Lo Line 315MHz | GK | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Tucson | 01/2022-12/2022 | Continental 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Hyundai | Tucson | 01/2021-12/2021 | Continental 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-----------|-----------------|-------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Hyundai | Tucson | 05/2015-09/2021 | Hi Line 433MHz | TL | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Tucson | 09/2014-12/2015 | 315MHz | LM | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Tucson | 04/2014-12/2017 | FUEL CELL 315MHz | LM FCEV | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Tucson | 08/2013-08/2014 | 315MHz | LM | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Tucson | 01/2010-07/2013 | 315MHz | LM | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Tucson | 01/2008-12/2009 | 315MHz | JM | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Tucson | 01/2004-12/2007 | 315MHz | JM | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Veloster | 01/2018-12/2022 | 433MHz | JS | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Veloster | 01/2019-12/2020 | FS 433MHz | FS | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Veloster | 01/2011-12/2019 | 315MHz | FS | ● | ● | ○ | 0/A | 315MHz | Schrader | ● | ● |
| Hyundai | Venue | 01/2020-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Hyundai | Veracruz | 01/2013-12/2013 | Lo Line 315MHz | EN | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Veracruz | 01/2008-12/2012 | Lo Line 315MHz | EN | ● | ● | ○ | 0 | 315MHz | Lear | ● | ● |
| Hyundai | Veracruz | 01/2006-12/2008 | Hi Line 315MHz | EN | ● | ● | ○ | 0 | 315MHz | Huf/Beru | ● | ● |
| Hyundai | i30 | 04/2012-12/2014 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Infiniti | EX Series | 11/2007-01/2011 | 315MHz 40700JK00C | J50 | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | EX Series | 01/2008-12/2008 | 315MHz 40700CD001 | J50 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Infiniti | EX Series | 04/2010-09/2018 | 315MHz | J50 | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | FX Series | 07/2007-08/2010 | 315MHz | S51 | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | FX Series | 09/2010-09/2019 | 315MHz | S51 | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | FX Series | 01/2007-12/2009 | 315MHz | JA60 | ○ | ● | ○ | C | 315MHz | Schrader | ● | ● |
| Infiniti | FX Series | 11/2002-06/2007 | 315MHz | S50 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Infiniti | G Series | 01/2007-12/2007 | Sedan 315MHz | V36 | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | G Series | 01/2007-12/2007 | Coupe 315MHz | V36 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Infiniti | G Series | 01/2002-12/2009 | 315MHz | V35 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Infiniti | G Series | 01/2007-03/2010 | 315MHz | V36 | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | G Series | 04/2010-12/2015 | 315MHz | V36 | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | JX35 | 09/2012-07/2020 | 433MHz | L50 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Infiniti | M Series | 07/2002-12/2008 | 315MHz | Y34 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Infiniti | M Series | 01/2011-12/2013 | 315MHz | Y51 | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | M Series | 01/2008-12/2010 | 315MHz | Y50 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Infiniti | Q25 | 01/2011-12/2012 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | Q30 | 01/2015-12/2021 | 433MHz | GD1A/H15 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Infiniti | Q40 | 01/2015-06/2018 | 315MHz | V36 | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | Q45 | 09/2006-12/2007 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Infiniti | Q45 | 08/2002-08/2006 | 315MHz | F50 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Infiniti | Q50 | 01/2013-12/2015 | 315MHz | V37 | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Infiniti | Q50 | 01/2016-12/2021 | 433MHz | V37 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Infiniti | Q60 | 05/2016-12/2021 | 433MHz | CV37 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Infiniti | Q60 | 01/2013-12/2017 | 315MHz | CV36/HV36 | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | Q70 | 01/2014-12/2020 | 315MHz | Y51 | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-------------|-----------------|--------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Infiniti | Q80 | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | QX30 | 09/2015-12/2020 | 433MHz | GD1A/H15 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Infiniti | QX4 | 01/1996-12/2006 | 315MHz | JR50 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Infiniti | QX40 | 01/2003-12/2003 | 315MHz | JR50 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Infiniti | QX50 | 11/2017-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Infiniti | QX50 | 01/2013-12/2018 | 315MHz | J50 | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | QX55 | 01/2022-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Infiniti | QX56 | 01/2004-04/2007 | 315MHz | JA60 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Infiniti | QX56 | 05/2007-05/2010 | 315MHz | JA60 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Infiniti | QX56 | 06/2010-12/2013 | 315MHz | Z62 | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | QX60 | 02/2012-12/2022 | 433MHz | L50 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Infiniti | QX70 | 01/2014-06/2019 | 315MHz | S51 | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | QX80 | 01/2014-12/2016 | 315MHz | Z62 | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | QX80 | 08/2016-05/2020 | 433MHz | Z62 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | QX80 | 01/2017-12/2021 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Isuzu | Ascender | 01/2006-12/2011 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Isuzu | Rodeo | 01/2004-12/2004 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Isuzu | i-290 | 01/2007-06/2011 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Isuzu | i-370 | 01/2007-12/2011 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| JAC | IEV S4 | 09/2019-12/2020 | 433MHz | | ○ | ● | ○ | C | 433MHz | JAC | ● | ● |
| JAC | Refine S2 | 01/2015-12/2020 | Steel 433MHz | | ● | ● | ○ | C | 433MHz | JAC | ● | ● |
| JAC | Refine S2 | 01/2015-12/2020 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| JAC | Refine S3 | 01/2014-12/2020 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| JAC | Refine S4 | 08/2019-12/2020 | 433MHz | | ● | ● | ○ | C | 433MHz | Schrader | ● | ● |
| JAC | Refine S5 | 01/2015-12/2020 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| JAC | T6 | 01/2015-12/2020 | SCH 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| JAC | T8 | 04/2020-06/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| JETOUR | X70 | 06/2018-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| JETOUR | X70M | 03/2020-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Jaguar | E-Pace | 01/2017-06/2021 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Pace | 01/2015-12/2022 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Type | 01/2014-12/2015 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Type | 01/2014-12/2017 | 315MHz | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Jaguar | F-Type | 01/2017-06/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Type | 01/2016-12/2016 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | I-Pace | 01/2017-06/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | S-Type | 01/2008-12/2011 | 315MHz | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Jaguar | S-Type | 01/2005-12/2009 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | S-Type | 01/2005-12/2007 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Jaguar | Super V8 | 01/2005-12/2006 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | Super V8 | 01/2005-12/2009 | 315MHz | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Jaguar | Super V8 | 01/2007-12/2009 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | Vanden Plas | 01/2007-12/2009 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | Vanden Plas | 01/2004-12/2006 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | Vanden Plas | 01/2004-12/2009 | 315MHz | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Jaguar | X-Type | 01/2007-12/2009 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|-----------|-----------------|---------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Jaguar | X-Type | 01/2007-12/2011 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Jaguar | XE | 01/2014-12/2016 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XE | 01/2015-12/2022 | GX631A159AA 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XF | 01/2014-09/2016 | FW931A159AB 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XF | 01/2008-12/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XF | 10/2016-12/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XF | 01/2009-12/2017 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Jaguar | XFR | 01/2010-12/2012 | 315MHz | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Jaguar | XFR | 01/2010-12/2012 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Jaguar | XJ | 01/2010-12/2020 | KR5S18005202 OA 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XJ | 01/2012-12/2021 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Jaguar | XJ | 01/2006-12/2011 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XJ | 01/2004-12/2011 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Jaguar | XJ | 01/2016-12/2021 | 433MHz | X351 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XK | 01/2005-12/2009 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Jaguar | XK | 01/2006-12/2009 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XK | 01/2010-12/2015 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Jaguar | XK | 01/2010-12/2015 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XK-S | 03/2014-12/2015 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XK-S | 01/2013-12/2014 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Jeep | Cherokee | 01/2019-12/2021 | 433MHz | KL | ● | ● | ○ | O/A | 433MHz | TRW | ● | ● |
| Jeep | Cherokee | 01/2018-12/2018 | 315MHz | | ● | ● | ○ | O/A | 315MHz | TRW | ● | ● |
| Jeep | Cherokee | 01/2018-12/2018 | 433MHz | KL | ● | ● | ○ | O/A | 433MHz | TRW | ● | ● |
| Jeep | Cherokee | 01/2016-12/2017 | 315MHz | | ● | ● | ● | O/A | 315MHz | TRW | ● | ● |
| Jeep | Cherokee | 12/2015-12/2017 | 433MHz | KL | ● | ● | ● | O/A | 433MHz | TRW | ● | ● |
| Jeep | Cherokee | 10/2013-11/2015 | 433MHz | KL | ● | ● | ● | O/A | 433MHz | TRW | ● | ● |
| Jeep | Cherokee | 01/2018-12/2022 | 433MHz 68324960AA | | ● | ● | ○ | O/A | 433MHz | TRW | ● | ● |
| Jeep | Cherokee | 01/2005-12/2013 | 433MHz 56029359AC | KK | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Commander | 01/2008-12/2011 | 433MHz | XK | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Commander | 01/2006-12/2007 | 315MHz | XK | ● | ● | ● | O/A | 315MHz | Schrader | ● | ● |
| Jeep | Commander | 01/2006-12/2007 | 433MHz | XK | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Jeep | Compass | 01/2015-12/2015 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Compass | 01/2012-12/2016 | 315MHz | MK49 | ● | ● | ● | O/A | 315MHz | Schrader | ● | ● |
| Jeep | Compass | 01/2012-12/2012 | SCH 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Compass | 01/2010-12/2011 | 315MHz | MK49 | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Jeep | Compass | 01/2008-12/2009 | 315MHz | MK49 | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Jeep | Compass | 01/2007-12/2007 | 315MHz | MK49 | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Jeep | Compass | 05/2006-12/2014 | VDO 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Jeep | Compass | 01/2019-12/2019 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Jeep | Compass | 01/2018-12/2018 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Jeep | Compass | 01/2018-01/2023 | 433MHz | MP/MX | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jeep | Compass | 01/2017-12/2017 | 433MHz | MP/MX | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Jeep | Compass | 01/2017-12/2017 | 315MHz | | ● | ● | ● | 0 | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|-----------------|-----------------|-------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Jeep | Gladiator | 11/2019-12/2022 | MRXAG4WA5 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Jeep | Gladiator | 01/2020-12/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Jeep | Gladiator | 01/2021-06/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Jeep | Gladiator | 07/2021-12/2022 | Conti 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Jeep | Grand Cherokee | 01/2022-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 04/2021-12/2022 | Conti 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jeep | Grand Cherokee | 01/2016-12/2017 | 433MHz | WK | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Jeep | Grand Cherokee | 06/2006-12/2010 | 433MHz | WH | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 01/2008-06/2010 | 433MHz | WK | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 07/2010-12/2010 | 433MHz | WK | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 01/2011-12/2011 | 433MHz | WK | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 01/2016-12/2022 | 433MHz 68252493AB | WK | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jeep | Grand Cherokee | 01/2014-12/2016 | 433MHz Schrader | WK | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 01/2012-12/2013 | 433MHz | WK | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 01/2001-12/2004 | 433MHz | WK/WJ | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 05/2004-12/2005 | 315MHz | WK | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Jeep | Grand Cherokee | 01/2005-05/2006 | 433MHz | | ● | ● | ● | O | 433MHz | Continental | ● | ● |
| Jeep | Grand Cherokee | 01/2006-12/2007 | 315MHz | WK | ● | ● | ● | O/A | 315MHz | Schrader | ● | ● |
| Jeep | Grand Commander | 01/2018-12/2022 | 433MHz | | ● | ● | ○ | O | 433MHz | TRW | ● | ● |
| Jeep | Grand Wagoneer | 01/2022-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Jeep | Liberty | 01/2005-12/2006 | 315MHz | KJ | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Jeep | Liberty | 01/2002-12/2004 | 433MHz | KJ | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Jeep | Liberty | 01/2006-12/2012 | 433MHz | KK | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Liberty | 01/2007-12/2009 | 315MHz | KJ | ● | ● | ● | O/A | 315MHz | Schrader | ● | ● |
| Jeep | Liberty | 01/2010-12/2012 | 315MHz | KK | ● | ● | ● | O/A | 315MHz | Schrader | ● | ● |
| Jeep | Patriot | 01/2007-12/2016 | 315MHz | MK | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Jeep | Patriot | 01/2011-12/2016 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Patriot | 01/2018-06/2019 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Jeep | Patriot | 01/2012-12/2017 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Jeep | Renegade | 01/2016-12/2017 | 433MHz 68252493AB | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jeep | Renegade | 01/2015-12/2016 | 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Jeep | Renegade | 01/2018-12/2022 | 433MHz 68193586AC | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jeep | Renegade | 01/2017-12/2017 | 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Jeep | Scrambler | 01/2020-12/2021 | DT 433MHz 68293199AA | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Jeep | Wagoneer | 01/2019-12/2022 | DT 433MHz 68293199AA | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Jeep | Wrangler | 07/2021-12/2022 | Conti 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jeep | Wrangler | 01/2010-12/2012 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Wrangler | 01/2021-06/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Wrangler | 01/2015-12/2017 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Wrangler | 01/2013-12/2014 | 433MHz | JK | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Wrangler | 01/2010-12/2012 | 315MHz | JK | ● | ● | ● | O/A | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|---------------|-----------------|----------------------|-------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Jeep | Wrangler | 06/2008-12/2010 | 433MHz | JK | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Wrangler | 01/2007-12/2009 | 315MHz | JK | ● | ● | ● | O/A | 315MHz | Schrader | ● | ● |
| Jeep | Wrangler | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| KIA | Amanti | 01/2009-12/2009 | 315MHz | GH | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Amanti | 01/2008-12/2008 | 315MHz | GH | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Amanti | 01/2007-12/2007 | 315MHz | GH | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Amanti | 01/2010-12/2011 | 315MHz | GH | ○ | ● | ○ | C | 315MHz | TRW | ● | ● |
| KIA | Borrego | 01/2008-12/2011 | 315MHz | HM | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Cadenza | 01/2016-12/2021 | 433MHz | YG | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Cadenza | 01/2013-12/2021 | 315MHz | VG | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| KIA | Cadenza | 01/2014-12/2017 | 433MHz | VG | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Carnival | 01/2022-12/2022 | 52940L1100 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| KIA | Carnival | 01/2022-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| KIA | Ceed | 05/2018-12/2020 | 433MHz | CD | ● | ● | ○ | O/A | 433MHz | Pacific | ● | ● |
| KIA | E-Niro | 10/2018-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | EV6 | 03/2021-12/2027 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| KIA | Forte | 01/2019-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| KIA | Forte | 04/2015-12/2018 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Forte | 02/2013-04/2015 | 315MHz | YD | ● | ● | ○ | O/A | 315MHz | TRW | ● | ● |
| KIA | Forte | 01/2009-04/2013 | 315MHz | TD | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| KIA | K2700 | 06/2014-12/2020 | 433MHz | PU | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| KIA | K3 | 07/2021-12/2022 | 433MHz | BD | ● | ● | ○ | O/A | 433MHz | Pacific | ● | ● |
| KIA | K5 | 01/2021-12/2022 | 433MHz | Clamp In OE | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| KIA | K5 | 01/2021-12/2022 | 433MHz | Snap In OE | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| KIA | K5 Hybrid | 01/2016-06/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| KIA | K5 Hybrid | 12/2013-12/2015 | 315MHz | | ○ | ● | ○ | C | 315MHz | Continental | ● | ● |
| KIA | K7 | 01/2016-12/2019 | 433MHz | YG | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | K7 | 01/2013-12/2016 | Hybrid 433MHz | VG | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | K7 | 01/2008-12/2012 | 433MHz | VG | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | K900 | 01/2019-12/2020 | 433MHz | RJ | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | K900 | 01/2014-12/2018 | 433MHz | KH | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Magentis | 12/2005-12/2010 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Lear | ● | ● |
| KIA | Mohave | 01/2016-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Mohave | 01/2009-12/2009 | Hi Line 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Niro | 01/2019-12/2021 | 433MHz | DE | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Niro | 01/2016-12/2018 | 433MHz | DE | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Optima | 07/2010-09/2013 | 315MHz | TF/QF | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| KIA | Optima | 12/2005-12/2010 | 315MHz | MG | ● | ● | ○ | 0 | 315MHz | Lear | ● | ● |
| KIA | Optima | 09/2015-12/2021 | 433MHz | JF/JFA | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Optima | 09/2013-12/2015 | 315MHz | TF/QF | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| KIA | Optima Hybrid | 01/2016-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Optima Hybrid | 01/2016-12/2016 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| KIA | Optima Hybrid | 01/2011-12/2015 | 315MHz | | ○ | ● | ○ | C | 315MHz | Continental | ● | ● |
| KIA | Quoris | 06/2012-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|---------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| KIA | Rio | 06/2017-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Rio | 06/2011-12/2017 | 315MHz | UB | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Rio | 01/2006-12/2017 | 315MHz | JB | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Rondo | 01/2013-06/2019 | 315MHz | RP | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| KIA | Rondo | 01/2006-12/2011 | 315MHz | UN | ● | ● | ○ | 0 | 315MHz | Lear | ● | ● |
| KIA | Sedona | 01/2019-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| KIA | Sedona | 01/2015-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Sedona | 01/2014-12/2014 | 433MHz | VQ | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Sedona | 06/2008-12/2014 | 315MHz | VQ | ● | ● | ○ | 0 | 315MHz | Lear | ● | ● |
| KIA | Sedona | 06/2005-06/2008 | 315MHz | VQ | ● | ● | ○ | 0 | 315MHz | Huf/Beru | ● | ● |
| KIA | Seltos | 01/2021-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| KIA | Sorento | 01/2005-12/2007 | 315MHz | BL | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Sorento | 01/2017-12/2023 | 433MHz 52933D4100 | UMA | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Sorento | 01/2014-06/2018 | 433MHz 529333N100 | UMA | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Sorento | 01/2014-12/2015 | 315MHz | XM | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| KIA | Sorento | 01/2013-12/2015 | 315MHz 529332M550 | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| KIA | Sorento | 01/2011-12/2013 | 315MHz | XM | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| KIA | Sorento | 01/2009-12/2010 | 315MHz Continental | BL | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| KIA | Sorento | 01/2009-12/2010 | 315MHz TRW | BL/XM | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Sorento | 01/2008-12/2008 | 315MHz | BL | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Soul | 01/2009-10/2013 | 315MHz | AM | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| KIA | Soul | 08/2013-12/2019 | 433MHz | PS | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Soul | 01/2019-12/2019 | 433MHz | SK3 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Soul | 01/2020-12/2021 | 433MHz | SK3 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Soul EV | 06/2014-12/2019 | 433MHz | PS EV | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Soul Electric | 06/2014-12/2019 | 433MHz | SK3 EV | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Spectra | 01/2006-12/2009 | Lo Line 315MHz | LD | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Spectra | 01/2010-12/2011 | Lo Line 315MHz | LD | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Sportage | 06/2014-12/2016 | 315MHz | SL | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Sportage | 01/2016-12/2023 | 433MHz | QL | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Sportage | 01/2009-12/2010 | Lo Line 315MHz | KM/SL | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Sportage | 01/2005-12/2007 | Lo Line 315MHz | KM | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Sportage | 01/2007-12/2007 | 315MHz 529332F000 | KM | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Sportage | 01/2008-12/2008 | Lo Line 315MHz | KM | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Sportage | 01/2008-12/2008 | 315MHz 529332F000 | KM | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Sportage | 01/2011-12/2013 | Lo Line 315MHz | KM/SL | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Sportage | 09/2013-06/2014 | 315MHz | SL | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Stinger | 06/2017-12/2017 | 433MHz | CK | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------------|---------------------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| KIA | Stinger | 01/2018-12/2022 | 433MHz | CK | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| KIA | Telluride | 01/2020-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| KIA | Telluride | 01/2019-12/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| KIA | Tuscany | 01/2007-12/2008 | 315MHz | YN | ○ | ● | ○ | C | 315MHz | TRW | ● | ● |
| Lamborghini | 140 Gallardo Superleggera | 01/2012-12/2012 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Lamborghini | Aventador | 01/2011-12/2022 | 433MHz | LB834 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Lamborghini | Aventador | 01/2010-12/2012 | 315MHz | | ○ | ● | ○ | C | 315MHz | Huf/Beru | ● | ● |
| Lamborghini | Gallardo | 01/2007-12/2014 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Lamborghini | Huracan | 01/2015-12/2016 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Lamborghini | Murcielago | 01/2007-12/2012 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Lamborghini | One off | 01/2016-12/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Lamborghini | Reventon | 01/2007-12/2010 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Lamborghini | Urus | 01/2018-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Land Rover | Defender | 01/2015-12/2015 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Defender | 01/2019-06/2023 | 433MHz LR070840 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery | 01/2016-12/2016 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Land Rover | Discovery | 01/2017-06/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery | 01/2017-12/2021 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Land Rover | Discovery Sport | 09/2015-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery Sport | 01/2015-08/2015 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery Sport | 01/2015-12/2016 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Land Rover | LR2 | 01/2006-12/2009 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | LR2 | 01/2010-12/2015 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | LR2 | 01/2008-12/2017 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Land Rover | LR3 | 01/2010-12/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | LR3 | 01/2004-12/2015 | Continental 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | LR3 | 01/2010-12/2014 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Land Rover | LR3 | 01/2002-12/2005 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Land Rover | LR3 | 01/2006-12/2009 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Land Rover | LR4 | 01/2010-12/2016 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Land Rover | LR4 | 01/2010-12/2016 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2007-12/2013 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2007-12/2009 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2006-12/2006 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2010-12/2013 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2002-12/2004 | 433MHz | L30 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Land Rover | Range Rover | 01/2017-12/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2016-12/2021 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2014-12/2016 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2014-12/2015 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2005-12/2006 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 01/2015-12/2016 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 01/2018-12/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|--------------------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Land Rover | Range Rover Evoque | 01/2011-12/2014 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 01/2014-12/2017 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Grand Evoque | 01/2017-12/2020 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 01/2016-12/2022 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 01/2005-12/2009 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 01/2006-12/2009 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 01/2010-12/2013 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 01/2010-12/2013 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 01/2014-12/2015 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 01/2014-12/2017 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Velar | 01/2017-06/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Velar | 01/2021-12/2022 | 433MHz (M8E21 A159AA) | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| LandWind | X5 | 01/2016-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TTE | ● | ● |
| LandWind | X7 | 01/2015-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TTE | ● | ● |
| Lexus | CT Series | 12/2010-12/2019 | PMVC010 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | CT Series | 12/2010-08/2017 | PMV107J 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | ES Series | 01/2020-12/2022 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | ES Series | 08/2006-06/2012 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | ES Series | 07/2012-07/2018 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | ES Series | 08/2018-12/2019 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | GS Series | 01/2005-03/2012 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | GS Series | 04/2012-12/2021 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | GS Series | 01/2012-12/2021 | 433MHz | 920L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | GX Series | 01/2004-03/2012 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | GX Series | 01/2021-12/2022 | PMVC015 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | GX Series | 04/2012-12/2022 | PMVC010 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | GX Series | 04/2012-08/2017 | PMV107J 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | HS Series | 07/2009-12/2012 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | IS Series | 09/2020-12/2022 | PMV-E000 315MHz | | ○ | ● | ○ | C | 315MHz | Pacific | ● | ● |
| Lexus | IS Series | 01/2006-07/2015 | PMV-107J 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | IS Series | 04/2013-12/2020 | PMV-C010 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | LC Series | 01/2018-12/2019 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | LC Series | 01/2020-12/2021 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|-------------|-----------------|-------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Lexus | LC Series | 01/2017-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | LFA | 12/2010-12/2013 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | LS 430 | 01/2004-12/2006 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Lexus | LS Series | 09/2012-12/2021 | Lo 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | LS Series | 10/2017-12/2021 | Hi 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | LS Series | 01/2007-08/2012 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | LX Series | 01/2015-12/2021 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | LX Series | 01/2013-12/2015 | PMVC010 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | LX Series | 01/2005-09/2015 | PMV107J 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | NX Series | 01/2014-12/2021 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | RC Series | 01/2020-12/2021 | PAXPMVE000 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | RC Series | 01/2014-12/2021 | PAXPMVC010 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | RX Series | 07/2013-09/2015 | 315MHz USA | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | RX Series | 01/2006-06/2013 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | RX Series | 10/2015-12/2020 | C015 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | RX Series | 01/2020-12/2022 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | RX Series | 07/2013-09/2015 | 315MHz Japan | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | SC Series | 08/2006-12/2010 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | UX Series | 10/2018-12/2021 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | UX Series | 01/2020-12/2021 | PMV-E100 433MHz | | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Lexus | UX Series | 05/2020-12/2021 | PMV-E000 315MHz | | ○ | ● | ○ | C | 315MHz | Pacific | ● | ● |
| Lifan | MaiWei | 01/2016-06/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | LiFan | ● | ● |
| Lincoln | Aviator | 05/2019-12/2022 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Lincoln | Aviator | 01/2003-12/2003 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Lincoln | Aviator | 01/2004-12/2004 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Lincoln | Aviator | 01/2005-12/2005 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Lincoln | Aviator | 01/2020-12/2020 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Lincoln | CUV | 01/2014-12/2018 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Lincoln | Continental | 01/2017-12/2017 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | Continental | 01/2018-12/2020 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | Continental | 01/2017-12/2020 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Lincoln | Corsair | 08/2019-12/2020 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Lincoln | Corsair | 08/2019-12/2021 | 315MHz | | ○ | ● | ○ | A/S | 315MHz | Schrader | ● | ● |
| Lincoln | MKC | 06/2015-12/2018 | 433MHz | 2.0F SEL | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Lincoln | MKC | 01/2016-12/2017 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | MKC | 01/2018-12/2020 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | MKC | 01/2015-12/2015 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | MKS | 01/2013-12/2016 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Lincoln | MKS | 01/2017-12/2019 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Lincoln | MKS | 01/2013-12/2016 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Lincoln | MKS | 01/2012-12/2012 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | MKS | 01/2011-12/2011 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|-----------|-----------------|-------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Lincoln | MKS | 01/2009-12/2010 | 315MHz | | ● | ● | ● | O/S | 315MHz | Continental | ● | ● |
| Lincoln | MKT | 01/2016-12/2019 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Lincoln | MKT | 01/2013-12/2015 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Lincoln | MKT | 01/2013-12/2015 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Lincoln | MKT | 08/2010-12/2012 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Lincoln | MKT | 01/2016-12/2017 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Lincoln | MKT | 01/2010-07/2010 | 315MHz | | ● | ● | ● | O/S | 315MHz | Continental | ● | ● |
| Lincoln | MKT | 01/2018-12/2020 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Lincoln | MKX | 01/2007-12/2007 | no Chrome rims 315MHz | | ● | ● | ○ | S | 315MHz | Continental | ● | ● |
| Lincoln | MKX | 01/2007-12/2007 | with Chrome rims 315MHz | | ● | ● | ○ | S | 315MHz | Continental | ● | ● |
| Lincoln | MKX | 01/2008-12/2010 | with Chrome rims 315MHz | | ● | ● | ● | O/S | 315MHz | Continental | ● | ● |
| Lincoln | MKX | 01/2008-12/2010 | no Chrome rims 315MHz | | ● | ● | ● | O/S | 315MHz | Continental | ● | ● |
| Lincoln | MKX | 01/2011-12/2011 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Lincoln | MKX | 07/2015-12/2019 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Lincoln | MKX | 01/2013-07/2015 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Lincoln | MKX | 02/2012-06/2015 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Lincoln | MKX | 01/2012-12/2012 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Lincoln | MKX | 08/2015-12/2021 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Lincoln | MKZ | 09/2015-12/2020 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Lincoln | MKZ | 01/2017-12/2021 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Lincoln | MKZ | 01/2013-12/2016 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Lincoln | MKZ | 01/2007-12/2007 | 315MHz | | ● | ● | ○ | S | 315MHz | Continental | ● | ● |
| Lincoln | MKZ | 01/2008-12/2009 | 315MHz | | ● | ● | ○ | S | 315MHz | Continental | ● | ● |
| Lincoln | MKZ | 01/2010-12/2012 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Lincoln | MKZ | 01/2013-08/2015 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Lincoln | Mark LT | 01/2015-12/2016 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Lincoln | Mark LT | 01/2013-12/2014 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Lincoln | Mark LT | 01/2010-12/2014 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Lincoln | Mark LT | 01/2009-12/2009 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Lincoln | Mark LT | 01/2008-12/2008 | Lear 315MHz | | ● | ● | ○ | S | 315MHz | Lear | ● | ● |
| Lincoln | Mark LT | 01/2007-12/2008 | VDO 315MHz | | ● | ● | ○ | S | 315MHz | Continental | ● | ● |
| Lincoln | Nautilus | 01/2019-12/2022 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Lincoln | Navigator | 01/2015-12/2015 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Lincoln | Navigator | 01/2013-12/2014 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Lincoln | Navigator | 01/2012-12/2014 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Lincoln | Navigator | 01/2011-12/2011 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Lincoln | Navigator | 01/2008-12/2010 | 315MHz | | ● | ● | ● | O/S | 315MHz | Continental | ● | ● |
| Lincoln | Navigator | 01/2007-12/2007 | 315MHz | | ● | ● | ○ | S | 315MHz | Continental | ● | ● |
| Lincoln | Navigator | 01/2005-12/2006 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Lincoln | Navigator | 01/2015-12/2015 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Lincoln | Navigator | 01/2016-12/2018 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Lincoln | Navigator | 01/2004-12/2004 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Lincoln | Navigator | 01/2018-12/2022 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|--------------|-----------------|-------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Lincoln | Navigator | 01/2003-12/2003 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Lincoln | Navigator | 01/2016-12/2017 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Lincoln | Town Car | 01/2012-12/2012 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Lincoln | Town Car | 01/2010-12/2011 | 315MHz | | ● | ● | ○ | S | 315MHz | Continental | ● | ● |
| Lincoln | Town Car | 01/2009-12/2009 | 315MHz | | ● | ● | ○ | S | 315MHz | Continental | ● | ● |
| Lincoln | Town Car | 01/2008-12/2008 | 315MHz | | ● | ● | ○ | S | 315MHz | Continental | ● | ● |
| Lincoln | Town Car | 01/2006-12/2007 | 315MHz | | ● | ● | ○ | S | 315MHz | Continental | ● | ● |
| Lincoln | Zephyr | 01/2010-12/2012 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Lincoln | Zephyr | 01/2006-12/2009 | 315MHz | | ● | ● | ○ | S | 315MHz | Continental | ● | ● |
| Lotus | 3 Eleven | 01/2014-12/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Lotus | Elise | 01/2008-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Lotus | Evora | 01/2010-12/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Lotus | Exige | 09/2000-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| MAXUS | G10 | 01/2014-12/2021 | Dias 433MHz | | ● | ● | ○ | O | 433MHz | Dias | ● | ● |
| MAXUS | G10 | 01/2014-12/2021 | 433MHz | | ● | ● | ○ | O | 433MHz | Dias | ● | ● |
| MAXUS | V80 | 01/2015-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Mahindra | Alturas G4 | 01/2018-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Maserati | Alfieri | 01/2020-06/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Maserati | Coupe | 07/2009-12/2013 | 433MHz | M145 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Maserati | Coupe | 01/2002-06/2009 | 433MHz | M145 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Maserati | Ghibli | 01/2013-12/2022 | 433MHz | M156/M157 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Maserati | GranCabrio | 01/2010-12/2013 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Maserati | GranSport | 01/2005-12/2006 | 433MHz | | ● | ● | ○ | O | 433MHz | Huf/Beru | ● | ● |
| Maserati | GranTurismo | 01/2017-12/2021 | 433MHz | M156/M157 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Maserati | GranTurismo | 01/2012-12/2015 | 315MHz | M145 GL | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Maserati | GranTurismo | 01/2011-12/2016 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Maserati | GranTurismo | 01/2008-12/2010 | 433MHz | M145 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Maserati | Levante | 01/2015-12/2022 | 433MHz | M161 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Maserati | Levante | 01/2018-12/2020 | 433MHz | M156D | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Maserati | Quattroporte | 01/2004-12/2010 | 433MHz | M139 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Maserati | Quattroporte | 01/2013-12/2022 | 433MHz | M156 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Maserati | Quattroporte | 01/2011-12/2013 | 433MHz | M139 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Maserati | Quattroporte | 01/2010-12/2012 | 315MHz | M139 | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Maserati | Spyder | 01/2002-12/2005 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Maybach | GLS SUV | 01/2019-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Maybach | Landulet | 01/2015-12/2019 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Maybach | Landulet | 01/2009-12/2012 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Huf/Beru | ● | ● |
| Maybach | Maybach 57 | 02/2002-12/2013 | 433MHz | Ma007 | ● | ● | ○ | O/S | 433MHz | Huf/Beru | ● | ● |
| Maybach | Maybach 57 | 01/2002-12/2012 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Huf/Beru | ● | ● |
| Maybach | Maybach 62 | 02/2002-12/2013 | 433MHz | Ma007 | ● | ● | ○ | O/S | 433MHz | Huf/Beru | ● | ● |
| Maybach | Maybach 62 | 01/2002-12/2012 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Huf/Beru | ● | ● |
| Maybach | S Series | 01/2015-12/2021 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Mazda | Atenza | 01/2016-12/2018 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | B Series LCV | 01/2006-12/2010 | 315MHz | | ○ | ● | ○ | S | 315MHz | Continental | ● | ● |
| Mazda | BT Pickup | 01/2020-12/2021 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|------------|-----------------|---------------------|------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Mazda | BT Pickup | 01/2006-12/2011 | 315MHz | | ○ | ● | ○ | S | 315MHz | Continental | ● | ● |
| Mazda | CX-3 | 01/2016-12/2020 | 315MHz | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-3 | 01/2021-12/2022 | 315MHz | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-3 | 01/2016-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | CX-30 | 01/2020-12/2022 | 315MHz | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-30 | 01/2019-06/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | CX-5 | 01/2020-12/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | CX-5 | 01/2020-12/2021 | 315MHz | | ○ | ● | ○ | C | 315MHz | Continental | ● | ● |
| Mazda | CX-5 | 01/2021-12/2022 | 315MHz BDGF37140 | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-5 | 01/2013-12/2015 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | CX-5 | 01/2016-12/2018 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | CX-5 | 01/2017-12/2020 | Direct 315MHz | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-5 | 01/2018-12/2019 | 433MHz | J53C/J72A | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | CX-6 | 01/2014-12/2015 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | CX-7 | 01/2006-12/2009 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-7 | 01/2010-12/2010 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-7 | 01/2011-12/2012 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-9 | 01/2007-12/2012 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-9 | 01/2013-12/2019 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-9 | 01/2016-12/2017 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | CX-9 | 01/2020-12/2021 | 315MHz | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | MX-5 | 01/2021-12/2022 | 315MHz | ND | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | MX-5 | 01/2018-12/2020 | 315MHz | ND | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | MX-5 | 01/2011-12/2014 | 433MHz | NC/J04C/J12 A | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | MX-5 | 05/2010-12/2018 | Indirect | ND | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | MX-5 | 03/2010-04/2015 | 315MHz | NC/J04C/J12 A | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | MX-5 | 12/2006-12/2008 | 315MHz | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | MX-5 Miata | 01/2016-05/2018 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | MX-5 Miata | 01/2005-12/2015 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | MX-5 Miata | 01/2021-12/2021 | 315MHz | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | MX-5 Miata | 06/2018-12/2020 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 2 | 01/2011-05/2014 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 2 | 06/2014-12/2015 | 315MHz | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 2 | 01/2019-12/2021 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Mazda | Mazda 3 | 01/2019-12/2021 | 315MHz | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 3 | 01/2014-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | Mazda 3 | 01/2011-12/2013 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 3 | 01/2010-12/2010 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 3 | 01/2007-12/2009 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 3 | 01/2005-12/2006 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 3 | 01/2004-12/2004 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 5 | 01/2014-12/2015 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | Mazda 5 | 01/2008-12/2010 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Mazda | Mazda 5 | 01/2016-12/2018 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 5 | 01/2011-12/2015 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 5 | 01/2005-12/2007 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 6 | 01/2011-12/2013 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 6 | 01/2014-12/2018 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | Mazda 6 | 01/2018-12/2021 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 6 | 01/2021-12/2022 | BDGF37140 315MHz | | ○ | ● | ○ | C | 315MHz | Continental | ● | ● |
| Mazda | Mazda 6 | 01/2005-12/2007 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 6 | 01/2008-12/2008 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 6 | 01/2009-12/2010 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | RX-8 | 01/2003-12/2004 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | RX-8 | 01/2005-12/2008 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | RX-8 | 01/2009-12/2010 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | RX-8 | 01/2011-12/2012 | 315MHz | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Speed 3 | 01/2007-12/2012 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Speed 6 | 01/2007-12/2008 | 315MHz | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Tribute | 01/2011-12/2013 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Mazda | Tribute | 01/2006-12/2007 | 315MHz | | ● | ● | ○ | S | 315MHz | Continental | ● | ● |
| Mazda | Tribute | 01/2010-12/2010 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Mazda | Tribute | 01/2009-12/2009 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Mazda | Tribute | 01/2008-12/2008 | 315MHz | | ○ | ● | ○ | S | 315MHz | Continental | ● | ● |
| McLaren | 500 Series | 01/2015-12/2021 | 433MHz RDE018 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | 500 Series | 01/2015-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | 600 Series | 03/2014-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | 700 Series | 01/2017-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | GT | 01/2019-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | MP4-12C | 01/2011-12/2014 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | P1 | 01/2013-12/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | Senna | 01/2017-12/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | Speedtail | 01/2019-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | A Class | 04/2014-05/2018 | 433MHz | W176 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | A Class | 06/2018-06/2022 | 433MHz | W177 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | AMG | 01/2013-06/2018 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | AMG GT | 11/2018-06/2021 | 433MHz | X290 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | AMG GT | 01/2014-06/2022 | 433MHz | C190 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | AMG GT | 11/2018-12/2021 | 315MHz | X290 | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Mercedes | B Class | 01/2011-12/2020 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | B Class | 02/2011-12/2022 | 433MHz A0009054104 | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | C Class | 09/2014-05/2018 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | C Class | 06/2018-12/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | C Class | 01/2007-08/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | CL Class | 10/2006-12/2010 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Mercedes | CL Class | 01/2000-09/2006 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | CL Class | 01/2010-12/2015 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-----------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Mercedes | CL Class | 01/2000-12/2007 | OYGRDKS-RE 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | CL Class | 10/2006-12/2010 | Continental 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Mercedes | CLA Class | 01/2014-12/2019 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | CLA Class | 05/2019-12/2022 | 433MHz | C118 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | CLK Class | 01/2002-12/2010 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | CLK Class | 01/2006-12/2009 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | CLS Class | 01/2017-12/2022 | 433MHz | C257 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | CLS Class | 01/2005-12/2005 | 433MHz | W219 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | CLS Class | 01/2006-12/2011 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Mercedes | CLS Class | 01/2012-12/2017 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | CLS Class | 01/2018-12/2019 | 433MHz | C218 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | CLS Class | 09/2004-12/2011 | Continental 433MHz | W219 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Mercedes | E Class | 01/2016-12/2022 | 433MHz | W213/BR238 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | E Class | 06/2010-12/2018 | 433MHz | W212 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | E Class | 01/1999-12/2005 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | E Class | 01/2000-12/2005 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | E Class | 01/2006-05/2010 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Mercedes | E Class | 01/2006-12/2010 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Mercedes | E Class | 07/2009-05/2014 | 433MHz | W212/C207 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | EQA | 01/2020-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | EQB | 01/2021-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | EQE | 01/2022-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | EQV | 01/2020-12/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | G Class | 04/2007-05/2018 | 433MHz | G463/461 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | G Class | 01/2018-12/2021 | 315MHz | G463 | ● | ● | ○ | 0/A | 315MHz | Schrader | ● | ● |
| Mercedes | G Class | 06/2018-12/2022 | 433MHz | G463 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | GL Class | 01/2006-12/2010 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Mercedes | GL Class | 04/2006-09/2009 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Mercedes | GL Class | 10/2009-12/2019 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLA Class | 01/2020-12/2022 | HUF 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | GLA Class | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Mercedes | GLA Class | 01/2014-12/2017 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLB Class | 01/2019-12/2022 | 433MHz | X247 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | GLC Class | 06/2015-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Mercedes | GLC Class | 01/2015-12/2021 | 315MHz | X253 | ● | ● | ○ | 0/A | 315MHz | Schrader | ● | ● |
| Mercedes | GLE Class | 07/2015-12/2020 | 433MHz | X166 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLE Class | 01/2018-12/2018 | 315MHz | W167 | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | GLE Class | 01/2021-12/2022 | 433MHz A0009052102 | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | GLE Class | 10/2018-12/2022 | 433MHz | V167 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | GLK Class | 01/2010-12/2017 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLS Class | 01/2015-06/2019 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLS Class | 07/2019-12/2022 | 433MHz | X167 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | GT | 01/2014-12/2022 | 433MHz | GT | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|---------------|-----------------|-----------------------|-------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Mercedes | GT-S | 01/2016-12/2019 | 433MHz | X166 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | GT-S AMG | 01/2019-12/2019 | 433MHz A0009052102 | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | GT-S AMG | 01/2014-12/2019 | 433MHz | C190 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | M Class | 01/2015-12/2015 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | M Class | 01/2005-12/2009 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Mercedes | M Class | 01/2010-12/2014 | 433MHz | W166 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | M Class | 01/2005-05/2011 | 433MHz | W164 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | ML Class | 01/2006-12/2010 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Mercedes | ML Class | 01/2006-05/2010 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | ML Class | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | ML Class | 06/2010-12/2016 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | Metris | 01/2015-12/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | R Class | 01/2010-12/2018 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | R Class | 01/2006-12/2009 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Mercedes | R Class | 01/2006-12/2009 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | S Class | 01/2000-12/2006 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | S Class | 01/2000-12/2006 | Huf 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | S Class | 12/2005-12/2013 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Mercedes | S Class | 01/2007-12/2009 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | S Class | 01/2010-12/2015 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | S Class | 01/2016-12/2017 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | S Class | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | S Class | 07/2020-06/2021 | 433MHz | C217 | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Mercedes | S Class | 01/2020-12/2022 | 433MHz | W223 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | S Class coupe | 01/2013-12/2020 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | SL Class | 01/2000-04/2005 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | SL Class | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | SL Class | 07/2012-12/2017 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | SL Class | 05/2005-12/2012 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Mercedes | SL Class | 05/2005-06/2012 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | SL Class | 01/2000-04/2005 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | SLC Class | 07/2020-12/2021 | 433MHz | R172 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | SLC Class | 01/2016-06/2020 | 433MHz | R172 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | SLK Class | 04/2007-05/2019 | 315MHz | R172 | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Mercedes | SLK Class | 01/2007-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | SLK Class | 01/2007-12/2007 | 433MHz | A0025400217 | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Mercedes | SLR Class | 01/2008-12/2010 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | SLR Class | 01/2008-12/2009 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Mercedes | SLR Class | 01/2001-12/2007 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | SLR Class | 01/2000-12/2007 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | SLR McLaren | 01/2008-12/2009 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Mercedes | SLR McLaren | 01/2004-12/2011 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | SLR McLaren | 01/2004-12/2007 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | SLS Class | 01/2010-12/2015 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | Sprinter | 01/2018-12/2022 | HUF 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|---------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Mercedes | Sprinter | 01/2018-12/2020 | SCH 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | Sprinter | 01/2010-12/2017 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | Sprinter | 01/2007-12/2014 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Mercedes | V Class | 01/2014-06/2021 | 433MHz | W447 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | X Class | 01/2017-12/2020 | 433MHz | | ● | ● | ○ | O | 433MHz | Pacific | ● | ● |
| Mercury | Grand Marquis | 01/2006-12/2007 | 315MHz | | ● | ● | ○ | S | 315MHz | Continental | ● | ● |
| Mercury | Grand Marquis | 01/2008-12/2008 | 315MHz | | ● | ● | ○ | S | 315MHz | Continental | ● | ● |
| Mercury | Grand Marquis | 01/2009-12/2011 | 315MHz | | ● | ● | ○ | S | 315MHz | Continental | ● | ● |
| Mercury | Mariner | 01/2005-12/2007 | 315MHz | | ● | ● | ○ | S | 315MHz | Continental | ● | ● |
| Mercury | Mariner | 01/2008-12/2008 | 315MHz | | ● | ● | ● | O/S | 315MHz | Continental | ● | ● |
| Mercury | Mariner | 01/2009-12/2009 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Mercury | Mariner | 01/2010-12/2010 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Mercury | Mariner | 01/2011-12/2011 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Mercury | Milan | 01/2007-12/2009 | 315MHz | | ● | ● | ○ | S | 315MHz | Continental | ● | ● |
| Mercury | Milan | 01/2010-12/2012 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Mercury | Montego | 01/2006-12/2007 | 315MHz | | ○ | ● | ○ | S | 315MHz | Continental | ● | ● |
| Mercury | Monterey | 01/2005-12/2005 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Mercury | Monterey | 01/2004-12/2004 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mercury | Monterey | 01/2004-12/2004 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Mercury | Monterey | 01/2005-12/2005 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mercury | Monterey | 01/2006-12/2007 | 315MHz | | ● | ● | ○ | S | 315MHz | Continental | ● | ● |
| Mercury | Mountaineer | 01/2004-12/2004 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Mercury | Mountaineer | 01/2005-12/2005 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Mercury | Mountaineer | 01/2006-12/2007 | 315MHz | | ● | ● | ○ | S | 315MHz | Continental | ● | ● |
| Mercury | Mountaineer | 01/2008-12/2010 | 315MHz | | ● | ● | ○ | S | 315MHz | Continental | ● | ● |
| Mercury | Mountaineer | 01/2002-12/2003 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Mercury | Sable | 01/2008-12/2009 | 315MHz | | ● | ● | ● | O/S | 315MHz | Continental | ● | ● |
| Mini | Cabrio | 01/2004-12/2006 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mini | Cabrio | 01/2010-06/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Cabrio | 07/2014-12/2020 | 433MHz | R57 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Cabrio | 01/2016-06/2021 | 433MHz | F57 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Cabrio | 01/2007-12/2009 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Mini | Clubman | 10/2006-07/2010 | 433MHz 36236798726 | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Mini | Clubman | 11/2013-12/2021 | 433MHz | F54 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Clubman | 10/2006-12/2015 | 433MHz 36106856227 | R55 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Clubvan | 01/2016-12/2019 | 433MHz | F54 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Clubvan | 07/2012-12/2015 | 433MHz | R55 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Convertible | 01/2014-12/2016 | 433MHz | R57 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Convertible | 01/2017-12/2021 | 433MHz | R57 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Cooper | 01/2010-12/2015 | OYGTSSRE4D 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Cooper | 03/2014-12/2021 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Cooper | 01/2007-12/2009 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Mini | Countryman | 07/2015-12/2022 | 433MHz | F60 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Countryman | 07/2014-12/2018 | 433MHz | R60 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|------------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Mini | Countryman | 01/2009-06/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Coupe | 01/2011-12/2016 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Coupe | 12/2010-09/2019 | 433MHz 36106856227 | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Hardtop | 01/2017-12/2021 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Hardtop | 01/2007-12/2009 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Mini | Hardtop | 01/2004-12/2006 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mini | Hardtop | 01/2010-12/2016 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Hatchback | 11/2013-12/2019 | 433MHz | F56 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Mini | 01/2009-12/2015 | OYGTSSRE4D 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Mini | 01/2007-12/2009 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Mini | Mini | 03/2006-12/2019 | 433MHz | F55/F56 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Mini | 01/2014-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Paceman | 01/2009-06/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Paceman | 07/2018-12/2019 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Paceman | 07/2014-06/2018 | 433MHz | R61 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Roadster | 01/2011-04/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Roadster | 05/2014-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mitsubishi | ASX | 04/2013-06/2013 | 315MHz | | ○ | ● | ○ | C | 315MHz | Continental | ● | ● |
| Mitsubishi | ASX | 04/2017-03/2020 | 315MHz | | ○ | ● | ○ | C | 315MHz | Continental | ● | ● |
| Mitsubishi | Colt Plus | 07/2016-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Mitsubishi | Eclipse | 01/2006-12/2009 | SCH 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Mitsubishi | Eclipse | 04/2007-12/2012 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Mitsubishi | Eclipse | 01/2017-12/2019 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Eclipse Cross | 03/2017-12/2021 | Snap-in 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Eclipse Cross | 01/2017-12/2022 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Eclipse Spyder | 11/2006-08/2011 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Mitsubishi | Endeavor | 01/2006-08/2010 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Mitsubishi | Endeavor | 09/2010-12/2012 | Steel 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Mitsubishi | Endeavor | 01/2003-08/2010 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Mitsubishi | Endeavor | 09/2006-12/2012 | Alloy 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Mitsubishi | Galant | 11/2009-12/2013 | Steel 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Mitsubishi | Galant | 01/2007-12/2010 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Mitsubishi | Galant | 07/2006-12/2013 | Alloy 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Mitsubishi | Galant | 01/2003-12/2006 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Mitsubishi | Heavy Duty | 01/2008-12/2009 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Mitsubishi | Lancer | 12/2006-12/2020 | 315MHz 4250B975 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Lancer | 01/2006-12/2010 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Lancer Sportback | 12/2008-07/2017 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Mirage | 07/2013-12/2021 | 315MHz 4250D585 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Mirage | 01/2014-12/2017 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Mirage G4 | 01/2014-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Mirage G4 | 01/2016-12/2017 | 4250B668 315MHz | | ○ | ● | ○ | C | 315MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|-----------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Mitsubishi | Mirage G4 | 03/2016-03/2020 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Montero | 01/2009-12/2015 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Montero | 01/2003-12/2006 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Mitsubishi | Montero Sport | 01/2016-03/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Montero Sport | 01/2003-12/2012 | 315MHz | | ○ | ● | ○ | C | 315MHz | Schrader | ● | ● |
| Mitsubishi | Montero Sport | 01/2016-12/2020 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Outlander | 03/2020-12/2021 | 315MHz | | ○ | ● | ○ | C | 315MHz | Continental | ● | ● |
| Mitsubishi | Outlander | 03/2018-12/2021 | Continental 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Outlander | 12/2006-12/2022 | 315MHz 4250B975 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Outlander | 05/2017-03/2021 | 315MHz 4250D585 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Outlander | 01/2006-12/2010 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Outlander PHEV | 11/2017-03/2020 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Outlander Sport | 04/2017-12/2021 | Snap-in 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Outlander Sport | 07/2010-12/2021 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Outlander sport | 07/2012-06/2013 | Snap-in 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | RVR | 01/2017-12/2021 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | RVR | 07/2012-06/2013 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | RVR | 01/2010-12/2021 | 315MHz 4250B975 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Raider | 01/2005-12/2010 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Mitsubishi | Shogun Sport | 01/2018-12/2019 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | i-MiEV | 01/2010-08/2017 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | 350Z | 06/2002-12/2006 | 315MHz | Z33 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | 350Z | 01/2007-12/2010 | 315MHz | Z33 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | 370Z | 10/2008-03/2010 | 315MHz | Z34 | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | 370Z | 05/2010-12/2022 | 315MHz | Z34 | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | 370Z | 01/2018-12/2018 | Non iKey 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Altima | 05/2012-09/2019 | 407003JA0B 433MHz | L33 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Altima | 01/2006-12/2011 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Altima | 01/2012-12/2014 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Altima | 10/2018-12/2022 | 433MHz | L33 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Altima Coupe | 01/2006-12/2013 | Coupe 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Altima Sedan | 01/2006-12/2012 | 315MHz | L33 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Ariya | 01/2022-12/2022 | 315MHz | | ○ | ● | ○ | C | 315MHz | Continental | ● | ● |
| Nissan | Ariya | 01/2022-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Nissan | Armada | 01/2014-12/2019 | MRXNG33MA4S 315MHz | | ○ | ● | ○ | C | 315MHz | Schrader | ● | ● |
| Nissan | Armada | 01/2007-12/2008 | 315MHz | TA60 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Armada | 08/2003-12/2006 | Alloy 315MHz | TA60 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Armada | 08/2003-12/2006 | Steel 315MHz | TA60 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Armada | 01/2009-12/2016 | 315MHz | TA60 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Armada | 01/2017-12/2017 | 433MHz | Y62 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|------------|-----------------|---------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Nissan | Armada | 06/2017-12/2022 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Armada GCC | 01/2013-12/2014 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Cima | 01/2017-06/2020 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Cima | 01/2012-12/2016 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Cube | 06/2012-02/2014 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Cube | 11/2011-11/2013 | 315MHz | B17 | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Cube | 01/2011-12/2015 | Smart key 315MHz | Z12 | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Cube | 01/2009-12/2015 | Standard key 315MHz | Z12 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Frontier | 01/2008-12/2008 | Alloy 315MHz | D40 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Frontier | 01/2009-12/2019 | 315MHz Schrader | D40 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Frontier | 01/2003-07/2004 | 315MHz | D22 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Frontier | 10/2004-12/2007 | 315MHz | D40 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Frontier | 01/2022-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Nissan | Frontier | 01/2020-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Frontier | 01/2016-12/2022 | 315MHz | D40 | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Frontier | 09/2006-12/2008 | Steel 315MHz | D40 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | GT-R | 05/2020-12/2022 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | GT-R | 01/2007-12/2022 | 315MHz | R35 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Juke | 01/2010-12/2017 | Standard key 315MHz | F15 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Juke | 07/2012-07/2015 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Juke | 01/2010-12/2020 | Smart key 315MHz | F15 | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Kicks | 10/2016-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Kicks | 01/2021-12/2022 | 315MHz | | ○ | ● | ○ | C | 315MHz | Pacific | ● | ● |
| Nissan | Leaf | 10/2010-12/2012 | 315MHz | ZE0 | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Leaf | 01/2013-12/2019 | 315MHz | ZE0 | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Leaf | 01/2017-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Leaf Korea | 01/2015-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | March | 01/2016-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Maxima | 01/2019-12/2022 | Snap in 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Maxima | 04/2015-12/2021 | Clamp in 433MHz | A36 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Maxima | 01/2003-12/2006 | 315MHz | A34 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Maxima | 01/2007-12/2007 | Steel 315MHz | A34 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Maxima | 01/2007-12/2007 | Alloy 315MHz | A34 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Maxima | 01/2008-12/2012 | MRXNG33MA4S 315MHz | A35 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Maxima | 01/2012-12/2014 | 315MHz | A35 | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Maxima | 01/2015-12/2017 | 315MHz | A35 | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Maxima GCC | 01/2013-12/2014 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Micra | 01/2014-02/2017 | 433MHz | K13 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Micra | 02/2017-12/2022 | 407004CB0B 433MHz | K14 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Micra | 03/2017-12/2021 | 433MHz | K14 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|------------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Nissan | Murano | 09/2002-07/2006 | 315MHz | Z50 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Murano | 01/2020-12/2022 | Snap in 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Murano | 10/2013-12/2022 | Clamp in 433MHz | Z52 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Murano | 11/2011-12/2015 | 315MHz Pacific | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Murano | 08/2006-09/2014 | 315MHz | Z51 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | NV1500/2500/3500 | 01/2011-12/2021 | 315MHz | F80 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | NV200 | 10/2014-12/2021 | Continental 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | NV200 | 11/2012-12/2017 | Schrader 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | NV200 Taxi | 01/2018-06/2021 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | NV200 Taxi | 01/2014-12/2017 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Note | 01/2013-12/2020 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Nissan | Pathfinder | 01/1996-12/2005 | 315MHz | R50 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Pathfinder | 01/2004-12/2006 | 315MHz | R51 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Pathfinder | 01/2007-12/2013 | 315MHz | R51 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Pathfinder | 01/2012-12/2012 | Continental 315MHz | | ○ | ● | ○ | C | 315MHz | Continental | ● | ● |
| Nissan | Pathfinder | 01/2013-10/2015 | 433MHz | R52 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Pathfinder | 11/2015-12/2020 | 433MHz | R52/P61B | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Pathfinder | 01/2019-12/2021 | 407009DJOA 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Nissan | Pathfinder | 01/2021-12/2022 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Nissan | Patrol | 01/2008-08/2016 | 433MHz | Y61 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Patrol | 01/2016-12/2019 | 433MHz | Y62 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Qashqai | 01/2016-05/2019 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Nissan | Qashqai | 06/2019-12/2021 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Nissan | Quest | 01/2005-12/2007 | Steel 315MHz | V42 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Quest | 11/2010-12/2019 | 315MHz | E52 | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Quest | 01/2008-12/2010 | 315MHz | V42 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Quest | 01/2005-12/2007 | Alloy 315MHz | V42 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Quest | 05/2003-12/2004 | 315MHz | V42 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Rogue | 01/2016-12/2016 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Nissan | Rogue | 01/2020-12/2022 | 315MHz | | ○ | ● | ○ | C | 315MHz | Continental | ● | ● |
| Nissan | Rogue | 10/2015-12/2020 | Korean 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Rogue | 10/2013-12/2019 | 433MHz | T32 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Rogue | 01/2008-12/2016 | Steel 315MHz | S35 | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Rogue | 01/2008-12/2016 | Alloy 315MHz | S35 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Rogue Select | 01/2014-12/2015 | 433MHz | S35 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Rogue Select | 01/2014-12/2019 | 315MHz | S35 | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Rogue Sport | 01/2017-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Sentra | 09/2006-05/2016 | 315MHz | B16 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Sentra | 09/2012-12/2016 | Smart key 315MHz | B17 | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|-----------------|-----------------|---------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Nissan | Sentra | 01/2018-12/2020 | Smart key 315MHz | B17 | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Sentra | 11/2012-12/2020 | Standard key 315MHz | B17 | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Sentra | 01/2016-07/2016 | 433MHz 407003AR1A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Sentra | 01/2017-12/2017 | Smart key 315MHz | B17 | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Sentra | 01/2020-12/2022 | 315MHz 407006LB0B | | ○ | ● | ○ | C | 315MHz | Pacific | ● | ● |
| Nissan | Skyline | 01/2014-12/2020 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Titan | 01/2015-12/2017 | 433MHz | A61 | ○ | ● | ○ | C | 433MHz | Pacific | ● | ● |
| Nissan | Titan | 01/2008-12/2008 | Alloy 315MHz | A60 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Titan | 10/2003-12/2007 | 315MHz | A60 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Titan | 01/2008-12/2008 | Steel 315MHz | A60 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Titan | 01/2018-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Titan | 01/2017-12/2022 | 433MHz 40700EZ00A | | ○ | ● | ○ | C | 433MHz | Pacific | ● | ● |
| Nissan | Titan | 01/2016-12/2017 | 315MHz | A61 | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Titan | 11/2015-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Titan | 09/2013-12/2015 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Titan | 01/2009-12/2015 | 315MHz | A60 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Titan Pro 4X | 12/2013-08/2015 | 315MHz | B17 | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Titan XD | 01/2018-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Titan XD | 01/2016-12/2017 | 433MHz | A61 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Versa | 05/2006-12/2008 | Steel 315MHz | SC11 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Versa | 01/2009-12/2012 | 315MHz | SC11 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Versa | 01/2012-06/2020 | Smart key 315MHz | N17 | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Versa | 01/2013-12/2021 | Standard key 315MHz | N17 | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Versa | 09/2014-05/2019 | 433MHz | N17 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Versa | 01/2020-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Versa | 05/2006-12/2008 | Alloy 315MHz | SC11 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Versa Hatchback | 01/2007-12/2010 | 315MHz | SC11 | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Versa Note | 01/2019-12/2021 | 315MHz | | ○ | ● | ○ | C | 315MHz | Continental | ● | ● |
| Nissan | Versa Sedan | 06/2019-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Versa Sedan | 03/2020-12/2022 | 433MHz 407006LB0A | | ○ | ● | ○ | C | 433MHz | Pacific | ● | ● |
| Nissan | Versa Sedan | 03/2014-08/2021 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | X-Trail | 01/2021-12/2021 | 315MHz | | ○ | ● | ○ | C | 315MHz | Continental | ● | ● |
| Nissan | X-Trail | 09/2016-06/2021 | 433MHz | T32 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Xterra | 01/2012-06/2018 | 315MHz Schrader | N50 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Xterra | 01/2012-12/2015 | 315MHz | N50 | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Xterra | 01/2012-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Xterra | 01/2005-12/2011 | 315MHz | N50 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Xterra | 01/2003-12/2004 | 315MHz | WD22 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Oldsmobile | Alero | 01/1999-12/2000 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|------------|-----------------|-----------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Oldsmobile | Aurora | 01/2001-12/2003 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Pontiac | Aztek | 01/2003-12/2005 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Pontiac | Bonneville | 01/2000-12/2005 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Pontiac | G3 | 01/2008-12/2010 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Pontiac | G5 | 01/2009-12/2010 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Pontiac | G5 | 01/2007-12/2008 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Pontiac | G6 | 01/2009-12/2010 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Pontiac | G6 | 06/2007-12/2008 | Snap in 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Pontiac | G6 | 06/2007-12/2008 | Clamp in 315MHz | | ● | ● | ● | 0/S | 315MHz | Continental | ● | ● |
| Pontiac | G8 | 01/2009-12/2009 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Pontiac | G8 | 01/2008-12/2008 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Pontiac | Grand Am | 01/1999-12/2002 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Pontiac | Grand Prix | 01/2004-12/2006 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Pontiac | Grand Prix | 01/2006-12/2008 | Clamp in 315MHz | | ● | ● | ● | 0/S | 315MHz | Continental | ● | ● |
| Pontiac | Grand Prix | 08/2007-12/2008 | Snap in 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Pontiac | Montana | 01/2008-12/2009 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Pontiac | SV-6 | 01/2008-12/2009 | 315MHz | | ○ | ● | ○ | C | 315MHz | Schrader | ● | ● |
| Pontiac | Solstice | 12/2007-12/2008 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Continental | ● | ● |
| Pontiac | Solstice | 01/2009-12/2009 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Continental | ● | ● |
| Pontiac | Solstice | 01/2010-12/2010 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Continental | ● | ● |
| Pontiac | Torrent | 01/2007-12/2008 | Clamp in 315MHz | | ○ | ● | ○ | S | 315MHz | Continental | ● | ● |
| Pontiac | Torrent | 01/2008-12/2008 | Snap in 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Pontiac | Torrent | 01/2009-12/2009 | Snap in 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Pontiac | Torrent | 01/2009-12/2009 | Clamp in 315MHz | | ● | ● | ● | 0/S | 315MHz | Continental | ● | ● |
| Pontiac | Vibe | 01/2008-12/2010 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Pacific | ● | ● |
| Pontiac | Vibe | 01/2005-12/2007 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Pontiac | Wave | 01/2007-12/2009 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Porsche | 718(982) | 01/2017-12/2021 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911 | 01/2005-12/2012 | 315MHz | 997 | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | 911 | 07/2004-01/2012 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911 | 01/2011-12/2017 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | 911 | 02/2012-12/2016 | 433MHz | 991 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911 | 01/2017-12/2021 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911(991) | 01/2017-12/2020 | 433MHz | 991 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911(991) | 01/2017-12/2019 | 315MHz | 991 | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Porsche | 911(991) | 12/2011-12/2016 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | 911(991) | 01/2011-12/2016 | 433MHz | 991 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911(992) | 01/2019-12/2021 | 315MHz | 992 | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | 911(992) | 01/2017-12/2021 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911(997) | 09/2015-12/2019 | 315MHz | 997 | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Porsche | 911(997) | 09/2015-12/2019 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|-------------|-----------------|---------------------|--------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Porsche | 911 (997) | 01/2009-08/2015 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | 911 (997) | 04/2008-08/2015 | 433MHz | 997 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911 (997) | 02/2005-03/2008 | 433MHz | 997 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911 (997) | 01/2005-12/2008 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | 911 (Turbo) | 01/2007-12/2009 | 433MHz | 997T | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911 (Turbo) | 01/2007-12/2009 | 315MHz | 997T | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | 911 (Turbo) | 01/2017-12/2021 | 315MHz | 991T/992T | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Porsche | 911 (Turbo) | 01/2017-12/2021 | 433MHz | 991T/992T | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911 (Turbo) | 01/2010-12/2016 | 433MHz | 991T | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911 (Turbo) | 01/2010-12/2016 | 315MHz | 991T | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | 918 Spyder | 01/2015-12/2015 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Porsche | 918 Spyder | 01/2013-12/2015 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 918 Spyder | 01/2014-12/2016 | 5Q0907275 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Porsche | Boxster | 01/2009-12/2011 | 433MHz | 987 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Boxster | 01/2004-12/2008 | 315MHz | 987 | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Boxster | 01/2004-12/2008 | 433MHz | 987 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Boxster | 01/2017-12/2021 | 315MHz | 982/982SP | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Boxster | 03/2016-06/2022 | 433MHz | 982/982SP | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Boxster | 01/2012-12/2016 | 433MHz | 981 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Boxster | 01/2012-12/2016 | 315MHz | 981/981SP | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Boxster | 01/2009-12/2012 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Carrera GT | 01/2004-12/2006 | 315MHz | | ○ | ● | ○ | C | 315MHz | Huf/Beru | ● | ● |
| Porsche | Carrera GT | 09/2003-12/2011 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 01/2007-12/2010 | 433MHz | 9PA1 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 01/2002-12/2006 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 09/2017-12/2022 | 433MHz | 9YA | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 01/2002-12/2006 | 433MHz | 9PA | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 01/2015-12/2021 | 315MHz | 9YA | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 11/2014-08/2017 | 433MHz | 92A | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 01/2011-10/2014 | 433MHz | 92A | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 01/2010-12/2014 | 315MHz | 92A | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 01/2007-12/2010 | 315MHz | 9PA1 | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne S | 09/2017-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne S | 01/2007-12/2009 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne S | 01/2008-12/2009 | 315MHz | 4. 8L | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne S | 01/2010-12/2012 | 315MHz | 4. 8L | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne S | 01/2010-05/2014 | 433MHz | 4. 8L | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne S | 06/2014-08/2017 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayman | 01/2005-12/2008 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Cayman | 01/2005-12/2008 | 433MHz | 987/987C | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayman | 01/2009-12/2011 | 433MHz | 987 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayman | 01/2009-12/2012 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Cayman | 01/2012-12/2016 | 433MHz | 981 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayman | 01/2013-12/2016 | 315MHz | 2. 7L | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Cayman | 10/2016-06/2022 | 433MHz | 982/982C/CT 4-2 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------------|---------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Porsche | Cayman | 01/2017-12/2020 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayman | 01/2017-12/2021 | 315MHz | CT4-2 | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Porsche | GT3 | 01/2010-12/2016 | 433MHz | 996/997 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | GT3 | 01/2007-12/2011 | 315MHz | 997 | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Porsche | GT3 | 03/2006-12/2011 | 433MHz | 996 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | GT3 | 01/2007-12/2009 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | GT3 | 01/2018-12/2021 | 315MHz | 991 | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Porsche | GT3 | 01/2017-12/2021 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Porsche | GT3 | 01/2015-12/2015 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Porsche | GT3 | 01/2012-12/2017 | 315MHz | 991 | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Macan | 01/2018-12/2021 | 315MHz | 95B | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Macan | 01/2014-12/2021 | 433MHz | P0416/95B | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Macan | 01/2014-12/2017 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Panamera | 09/2013-08/2017 | 433MHz | 970 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Panamera | 01/2010-12/2013 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Panamera | 01/2009-06/2013 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Panamera | 09/2017-06/2021 | 433MHz | 970/971 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Panamera | 01/2017-12/2021 | 315MHz | 971 | ○ | ● | ○ | C | 315MHz | Huf/Beru | ● | ● |
| Porsche | Panamera | 01/2014-12/2016 | 315MHz | 970 | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Panamera S | 01/2009-06/2013 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Panamera S | 06/2009-12/2013 | 315MHz | 4. 8L | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Taycan | 01/2020-12/2021 | 315MHz | | ○ | ● | ○ | C | 315MHz | Huf/Beru | ● | ● |
| Porsche | Taycan | 01/2019-12/2022 | 433MHz 9J1907275 | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Renault Samsung | QM3 | 01/2013-12/2015 | 433MHz | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Renault Samsung | QM5 | 01/2014-12/2016 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Renault Samsung | QM6 | 01/2016-12/2016 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Renault Samsung | SM3 | 01/2013-12/2015 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Renault Samsung | SM5 | 01/2010-12/2018 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Renault Samsung | SM6 | 01/2015-12/2020 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Renault Samsung | SM7 | 01/2012-12/2015 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Retrofit | E-LEAD | 01/2020-12/2020 | 433MHz | | ○ | ● | ○ | S | 433MHz | E-LEAD | ● | ● |
| Retrofit | Honda-CRV | 01/2020-12/2021 | 433MHz | | ○ | ● | ○ | S | 433MHz | E-LEAD | ● | ● |
| Retrofit | Honda-fit | 01/2016-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Cub | ● | ● |
| Retrofit | ORO W401 | 01/2018-06/2019 | 433MHz | | ○ | ● | ○ | S | 433MHz | ORO | ● | ● |
| Retrofit | ORO W410-A | 01/2018-06/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | ORO | ● | ● |
| Retrofit | ORO W410/W403 | 01/2018-06/2019 | 433MHz | | ○ | ● | ○ | S | 433MHz | ORO | ● | ● |
| Retrofit | ORO W417-A | 01/2019-12/2019 | 433MHz | | ○ | ● | ○ | A/S | 433MHz | ORO | ● | ● |
| Retrofit | ORO W418-A | 01/2018-06/2019 | 433MHz | | ○ | ● | ○ | A/S | 433MHz | ORO | ● | ● |
| Rolls Royce | Black Badge | 01/2019-06/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Cullinan | 02/2018-12/2022 | YGOTSSRE4A 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------------|----------------|-----------------|-----------------------|-------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Rolls Royce | Cullinan | 01/2018-12/2021 | 433MHz | R31 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Rolls Royce | Dawn | 01/2016-12/2021 | 433MHz | RR6 | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Drophead Coupe | 06/2007-12/2018 | 433MHz | RR02 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Ghost | 08/2008-12/2022 | 433MHz | 36106790054 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Ghost | 01/2010-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Ghost | 01/2009-12/2010 | 433MHz 36236798726 | RR04 | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Phantom | 01/2017-12/2022 | MRXAG5SP4 433MHz | RR11 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Rolls Royce | Phantom | 01/2007-12/2022 | OYGTSSRE4DB 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Phantom | 02/2003-12/2017 | OYGTSSRE4TC 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Phantom | 01/2012-12/2017 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Wraith | 05/2013-12/2022 | 433MHz | RR5 | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Wraith | 01/2012-12/2021 | OYGTSSRE4D 433MHz | RR5 | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| SWM | X7 | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | O | 433MHz | Mobiletron | ● | ● |
| Saab | 9-3 | 01/2008-12/2012 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Saab | 9-3 | 01/2003-12/2007 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Saab | 9-4X | 01/2011-12/2012 | 315MHz | | ● | ● | ● | O | 315MHz | Schrader | ● | ● |
| Saab | 9-5 | 01/2010-12/2012 | 315MHz | | ● | ● | ● | O/A | 315MHz | Schrader | ● | ● |
| Saab | 9-5 | 01/2008-12/2012 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Saab | 9-5 | 01/2003-12/2007 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Saab | 9-7X | 01/2008-12/2009 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Saab | 9-7X | 01/2005-12/2007 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Saturn | Astra | 01/2007-12/2008 | Clamp in 315MHz | | ○ | ● | ○ | C | 315MHz | Schrader | ● | ● |
| Saturn | Astra | 01/2010-12/2010 | 315MHz | | ○ | ● | ○ | C | 315MHz | Schrader | ● | ● |
| Saturn | Astra | 01/2010-12/2010 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Saturn | Astra | 01/2008-12/2009 | Snap in 315MHz | | ○ | ● | ○ | C | 315MHz | Schrader | ● | ● |
| Saturn | Astra | 01/2008-12/2009 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Saturn | Aura | 01/2008-12/2008 | Snap in 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Saturn | Aura | 01/2009-12/2010 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Saturn | Aura | 01/2007-12/2008 | Clamp in 315MHz | | ● | ● | ● | O/S | 315MHz | Continental | ● | ● |
| Saturn | Lambda | 01/2007-12/2008 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Saturn | Outlook | 01/2009-12/2010 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Saturn | Outlook | 01/2007-12/2008 | 315MHz | | ○ | ● | ○ | S | 315MHz | Continental | ● | ● |
| Saturn | Sky | 01/2010-12/2010 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Saturn | Sky | 01/2009-12/2009 | 315MHz | | ● | ● | ● | O/S | 315MHz | Continental | ● | ● |
| Saturn | Sky | 01/2008-12/2008 | 315MHz | | ● | ● | ● | O/S | 315MHz | Continental | ● | ● |
| Saturn | Vue | 11/2008-12/2010 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Saturn | Vue | 01/2008-10/2008 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Saturn | Vue | 01/2007-12/2007 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Scion | Corolla iM | 01/2015-12/2016 | 315MHz | | ● | ● | ○ | O | 315MHz | Pacific | ● | ● |
| Scion | FR-S | 01/2013-12/2016 | 315MHz | | ● | ● | ○ | O | 315MHz | Pacific | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|--------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Scion | IQ | 01/2012-12/2015 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Scion | TC | 08/2010-05/2013 | C11A 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Scion | TC | 01/2006-12/2016 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Scion | Tc | 01/2005-05/2006 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Scion | XB | 01/2007-12/2016 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Scion | XD | 01/2008-12/2016 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Scion | iA | 01/2015-06/2017 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Scion | iM | 01/2015-05/2018 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Smart | 42 EV | 01/2013-12/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Smart | Forfour | 01/2005-12/2021 | 433MHz | A453 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Smart | Fortwo | 01/2014-12/2022 | 433MHz | A453 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Smart | Fortwo | 01/2008-12/2015 | 433MHz | A451 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Soueast | DX3 | 01/2016-12/2020 | Whetron 433MHz | | ● | ● | ○ | 0 | 433MHz | Whetron | ● | ● |
| Soueast | DX7 | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Soueast | DX7 | 10/2014-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Whetron | ● | ● |
| Soueast | DX7 | 01/2014-06/2019 | Steel Mate 433MHz | | ● | ● | ○ | 0 | 433MHz | Steel Mate | ● | ● |
| Subaru | Ascent | 01/2018-12/2022 | 433MHz | HR3 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Subaru | B9 Tribeca | 11/2004-03/2008 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Subaru | BRZ | 11/2011-12/2020 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Subaru | Crosstrek | 01/2018-12/2021 | 433MHz | HR3 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Subaru | Crosstrek | 01/2015-12/2017 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Subaru | Forester | 01/2007-06/2013 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Subaru | Forester | 01/2018-12/2021 | 433MHz | FM5/PF3 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Subaru | Forester | 07/2013-12/2019 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Subaru | Impreza | 09/2016-06/2022 | 433MHz | HR3 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Subaru | Impreza | 07/2013-12/2022 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Subaru | Impreza | 01/2008-06/2013 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Subaru | Impreza | 01/2007-12/2007 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Subaru | Legacy | 01/2019-12/2022 | 315MHz | | ○ | ● | ○ | C | 315MHz | Schrader | ● | ● |
| Subaru | Legacy | 05/2017-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Subaru | Legacy | 11/2003-04/2008 | 315MHz 28103AG00B | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Subaru | Legacy | 12/2006-06/2013 | 315MHz 28103AG01C | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Subaru | Legacy | 07/2013-06/2017 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Subaru | Outback | 01/2018-12/2021 | 433MHz | BS/BT | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Subaru | Outback | 07/2009-12/2017 | 28103AJ00A 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Subaru | Outback | 01/2008-06/2015 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Subaru | Outback | 01/2004-12/2007 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Subaru | Tribeca | 08/2013-12/2014 | 315MHz | | ○ | ● | ○ | C | 315MHz | Schrader | ● | ● |
| Subaru | Tribeca | 03/2008-07/2013 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Subaru | WRX | 11/2013-12/2022 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Subaru | XV Crosstrek | 04/2017-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Subaru | XV Crosstrek | 07/2013-06/2017 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Subaru | XV Crosstrek | 04/2012-06/2013 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|--------------|-----------------|-------------------|----------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Suzuki | Equator | 01/2009-12/2013 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Suzuki | Forenza | 01/2007-12/2008 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Suzuki | Grand Vitara | 01/2005-12/2014 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Suzuki | Jimny 3 | 01/2021-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Kizashi | 01/2010-12/2014 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Suzuki | Reno | 01/2007-12/2008 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Suzuki | SX4 | 01/2007-12/2014 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Suzuki | Super Carry | 01/2019-12/2019 | 433MHz | | ○ | ● | ○ | C | 433MHz | Orange | ● | ● |
| Suzuki | Verona | 01/2005-12/2006 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Suzuki | XL-7 | 07/2006-12/2011 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Suzuki | XL-7 | 01/2005-06/2006 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Tesla | Model 3 | 01/2016-06/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Tesla | Model S | 10/2014-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Tesla | Model S | 01/2012-09/2014 | 433MHz | | ○ | ● | ○ | A | 433MHz | Baolong | ● | ● |
| Tesla | Model X | 01/2016-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Tesla | Roadster | 01/2010-12/2012 | Baolong 433MHz | | ○ | ● | ○ | A | 433MHz | Baolong | ● | ● |
| Tesla | Roadster | 01/2008-12/2010 | Huf 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Toyota | 4 Runner | 01/2020-12/2022 | Clamp in 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | 4 Runner | 09/2017-12/2019 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | 4 Runner | 09/2006-08/2017 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | 4 Runner | 01/2003-08/2006 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | 4 runner | 01/2020-12/2021 | Snap in 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | 86 | 07/2016-12/2020 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | ALLION | 04/2021-12/2021 | 433MHz | | ○ | ● | ○ | C | 433MHz | Pacific | ● | ● |
| Toyota | Alphard | 01/2015-01/2020 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Auris | 01/2019-12/2019 | 315MHz | 130A/130L/142L | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Avalon | 10/2015-12/2019 | 315MHz PAXPMVC015 | | ● | ● | ○ | O/A | 315MHz | Pacific | ● | ● |
| Toyota | Avalon | 01/2006-10/2012 | Japan/USA 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Avalon | 11/2012-12/2019 | 315MHz PAXPMVC010 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Avalon | 01/2020-12/2022 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Avanza | 09/2016-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | C-HR | 01/2020-12/2021 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | C-HR | 10/2016-12/2019 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Pacific | ● | ● |
| Toyota | C-HR | 01/2016-12/2021 | 433MHz | 560A | ● | ● | ○ | O/A | 433MHz | Pacific | ● | ● |
| Toyota | Camry | 09/2014-12/2022 | Clamp in 315MHz | | ● | ● | ○ | O/A | 315MHz | Pacific | ● | ● |
| Toyota | Camry | 01/2020-12/2022 | Snap in 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Camry | 10/2011-12/2019 | C010 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Camry | 01/2006-09/2011 | Japan/USA 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Camry | 01/2004-12/2005 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|--------------------|-----------------|---------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Toyota | Camry Hybrid | 09/2014-12/2020 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Pacific | ● | ● |
| Toyota | Corolla | 08/2013-12/2019 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Corolla | 01/2019-12/2022 | E000 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Corolla | 01/2006-08/2013 | Japan/USA 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Corolla | 01/2005-06/2007 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Toyota | Corolla Cross | 01/2022-12/2023 | Clamp in 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Corolla Hatchback | 01/2019-12/2022 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Corolla iM | 06/2015-12/2019 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | FJ Cruiser | 06/2014-12/2020 | 433MHz | 155L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | FJ Cruiser | 01/2007-12/2014 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | FR-S | 01/2017-12/2019 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | GR Supra | 01/2019-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Huf/Beru | ● | ● |
| Toyota | GT86 | 01/2017-12/2021 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Hiace | 06/2014-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Highlander | 01/2014-12/2017 | Smart Key 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Highlander | 01/2007-12/2013 | Japan/USA 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Highlander | 01/2020-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Highlander | 01/2021-12/2022 | 426070E040 433MHz | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Toyota | Highlander | 01/2004-12/2006 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Toyota | Highlander | 12/2019-12/2021 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Toyota | Highlander | 01/2018-12/2019 | Smart Key 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Highlander | 01/2014-12/2019 | Standard Key 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Toyota | Highlander hybrids | 12/2019-12/2020 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Toyota | Hilux | 06/2020-12/2021 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Hilux | 01/2009-12/2021 | 433MHz | 669L/640A | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Innova | 09/2016-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Land Cruiser | 01/2020-12/2021 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Land Cruiser | 10/2015-12/2019 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Land Cruiser | 01/2006-09/2015 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Land Cruiser | 01/2005-12/2005 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Land Cruiser Prado | 10/2017-12/2021 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Land Cruiser Prado | 01/2014-09/2017 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Matrix | 01/2007-12/2014 | Japan/USA 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Mirai | 11/2020-12/2022 | C015 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Mirai | 01/2019-08/2022 | PMVC215 433MHz | 045L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Mirai | 01/2016-12/2022 | C010 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Prius | 01/2006-12/2012 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|-------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Toyota | Prius | 01/2019-12/2022 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Prius | 01/2016-12/2018 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Prius | 01/2013-12/2015 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Prius C | 12/2011-12/2021 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Prius Prime | 01/2016-12/2021 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Prius Prime | 01/2020-12/2022 | Clamp in 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Prius V | 01/2017-12/2019 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Prius V | 01/2012-12/2016 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | RAV4 | 01/2019-12/2021 | C015 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | RAV4 | 12/2018-12/2021 | TRW 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Toyota | RAV4 | 01/2013-12/2018 | TRW 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Toyota | RAV4 | 01/2013-12/2018 | Pacific 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | RAV4 | 11/2005-12/2012 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | RUSH | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Sequoia | 08/2017-12/2019 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Toyota | Sequoia | 01/2020-12/2022 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Sequoia | 01/2009-07/2017 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Toyota | Sequoia | 01/2008-12/2008 | Alloy/Steel 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Toyota | Sequoia | 01/2004-12/2007 | Alloy/Steel 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Sienna | 01/2021-12/2022 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Toyota | Sienna | 01/2021-12/2021 | C215 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Sienna | 01/2013-02/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Toyota | Sienna | 01/2006-12/2020 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Toyota | Sienta | 11/2016-12/2019 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Solara | 01/2006-12/2011 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Supra | 03/2019-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Toyota | Supra | 03/2019-12/2022 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Toyota | Tacoma | 01/2010-08/2015 | Steel 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Tacoma | 01/2010-08/2015 | Alloy 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Tacoma | 01/2005-12/2009 | Steel 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Tacoma | 01/2005-12/2009 | Alloy 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Tacoma | 01/2020-12/2022 | PAXPMVE000 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Tacoma | 09/2015-12/2022 | PAXPMVC015 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Tundra | 01/2020-12/2022 | Alloy 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Tundra | 01/2005-12/2006 | Alloy 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Tundra | 01/2005-12/2006 | Steel 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Tundra | 01/2020-12/2022 | Steel 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Tundra | 08/2017-12/2019 | Alloy 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Toyota | Tundra | 08/2017-12/2019 | Steel 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Toyota | Tundra | 01/2012-07/2017 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Toyota | Tundra | 01/2007-12/2011 | Alloy 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Toyota | Tundra | 01/2007-12/2011 | Steel 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|-------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Toyota | Venza | 01/2021-12/2022 | 315MHz | | ● | ● | ○ | O | 315MHz | Pacific | ● | ● |
| Toyota | Venza | 01/2009-12/2016 | 315MHz | | ● | ● | ○ | O | 315MHz | Pacific | ● | ● |
| Toyota | Vios | 01/2012-12/2021 | 315MHz | | ● | ● | ○ | O | 315MHz | Pacific | ● | ● |
| Toyota | Yaris | 01/2017-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Toyota | Yaris | 01/2012-06/2021 | 315MHz | | ● | ● | ○ | O | 315MHz | Pacific | ● | ● |
| Toyota | Yaris | 01/2007-12/2011 | 315MHz | | ● | ● | ○ | O | 315MHz | Pacific | ● | ● |
| Toyota | Yaris Sedan | 01/2020-12/2020 | 315MHz | | ○ | ● | ○ | C | 315MHz | Huf/Beru | ● | ● |
| Toyota | iA | 01/2017-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Toyota | iM | 01/2017-12/2019 | 315MHz | | ● | ● | ○ | O | 315MHz | Pacific | ● | ● |
| VPG | MV-1 | 01/2011-12/2016 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Volkswagen | Amarok | 03/2018-12/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Amarok | 01/2014-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Amarok | 11/2009-02/2018 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Arteon | 01/2017-12/2021 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Arteon | 01/2017-12/2020 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Volkswagen | Atlas | 01/2017-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Atlas | 01/2017-12/2020 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Beetle | 01/2006-12/2011 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Volkswagen | Beetle | 01/2012-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Bora | 01/2005-12/2010 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Volkswagen | CC | 01/2018-12/2021 | MQB 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | CC | 06/2011-12/2020 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | CC | 01/2009-12/2011 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Volkswagen | Crafter | 01/2006-12/2016 | 433MHz Continental | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Volkswagen | EOS | 01/2006-12/2017 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Volkswagen | GLI | 01/2008-12/2011 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Volkswagen | GTI | 01/2006-12/2012 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Volkswagen | GTI | 01/2012-12/2021 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Volkswagen | Golf | 01/2012-12/2012 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Volkswagen | Golf | 01/2009-12/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Golf | 01/2008-12/2014 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Volkswagen | Golf | 01/2006-12/2007 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Volkswagen | Golf | 01/2013-12/2021 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Volkswagen | Jetta | 01/2013-12/2022 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Volkswagen | Jetta | 01/2013-12/2019 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Jetta | 01/2011-12/2012 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Volkswagen | Jetta | 01/2005-12/2014 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Volkswagen | New Beetle | 01/2012-12/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | New Beetle | 01/2006-12/2011 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Volkswagen | Passat | 09/2014-06/2021 | 433MHz | B8 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Passat | 01/2012-12/2021 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Volkswagen | Passat | 01/2010-12/2015 | 433MHz | B6/VW471 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Passat | 01/2006-12/2011 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Volkswagen | Passat | 01/2005-12/2011 | 433MHz | VW451 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volkswagen | Passat | 01/2015-06/2020 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|-----------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Volkswagen | Passat CC | 03/2008-12/2016 | 3AA907275 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Passat CC | 01/2009-12/2012 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Volkswagen | Phaeton | 01/2011-12/2012 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Phaeton | 06/2007-12/2010 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Volkswagen | Phaeton | 06/2007-12/2010 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Phaeton | 01/2003-05/2007 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Volkswagen | Phaeton | 01/2003-05/2007 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | R32 | 01/2006-12/2011 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Volkswagen | R320 | 01/2008-12/2008 | 315MHz | | ○ | ● | ○ | C | 315MHz | Continental | ● | ● |
| Volkswagen | R36 | 01/2009-12/2011 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Volkswagen | Rabbit | 01/2006-12/2011 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Volkswagen | Routan | 01/2011-12/2015 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Volkswagen | Routan | 01/2009-12/2010 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volkswagen | Routan | 01/2005-12/2008 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Volkswagen | T-Cross | 01/2019-06/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | T-ROC | 11/2017-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Tiguan | 01/2016-12/2020 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Volkswagen | Tiguan | 01/2012-12/2015 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Tiguan | 01/2011-12/2021 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Volkswagen | Tiguan | 01/2008-12/2011 | 315MHz | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Volkswagen | Tiguan | 01/2016-12/2020 | 433MHz | VW376/5N2 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Tiguan L | 01/2016-12/2020 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Touareg | 01/2015-12/2018 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Volkswagen | Touareg | 08/2014-12/2021 | 433MHz | 7P5/7P6108 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Touareg | 01/2012-12/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Touareg | 01/2007-12/2011 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Touareg | 02/2002-12/2007 | 433MHz | 7L | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Touareg | 01/2007-12/2016 | 315MHz 7PP907275G | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Volkswagen | Vento | 01/2005-12/2014 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Volvo | C30 | 01/2011-03/2014 | 433MHz | Y279 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | C30 | 01/2006-12/2010 | 433MHz | Y279 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | C70 | 01/2011-06/2014 | 433MHz | V70064 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | C70 | 01/2008-12/2010 | 433MHz | V70064 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | C70 | 01/2006-12/2007 | 433MHz | V70064 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S40 | 01/2011-06/2014 | 433MHz | V40044 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S40 | 01/2003-12/2010 | 433MHz | V40044 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S60 | 01/2015-12/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S60 | 02/2013-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | S60 | 01/2011-12/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S60 | 01/2004-12/2010 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Volvo | S60 | 07/2000-02/2010 | 433MHz | P24/V664 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Volvo | S80 | 07/2014-01/2017 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S80 | 01/2013-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | S80 | 01/2010-06/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S80 | 01/2004-12/2009 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|-------------------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Volvo | S80 | 01/2004-12/2007 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Volvo | S90 | 01/2016-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | S90 | 01/2016-06/2021 | 433MHz | V541 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Volvo | V40 | 01/2012-12/2020 | 433MHz | Y555, Y556 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V50 | 01/2011-12/2012 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V50 | 01/2005-12/2010 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V60 | 11/2017-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Volvo | V60 | 01/2014-12/2019 | 433MHz 31341893 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V60 | 09/2015-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | V60 Cross Country Wagon | 01/2015-12/2018 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V70 | 01/2008-12/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V70 | 01/2000-12/2007 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Volvo | V70 | 01/2000-12/2007 | 433MHz | Y285/V764 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Volvo | V90 | 01/2016-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | V90 | 01/2015-06/2021 | 433MHz | V542 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Volvo | XC40 | 01/2017-12/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | XC60 | 01/2015-12/2021 | 433MHz | Y413 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | XC60 | 01/2015-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | XC60 | 01/2009-12/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | XC60 | 01/2009-12/2010 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Volvo | XC70 | 01/2015-12/2017 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | XC70 | 01/2015-12/2017 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | XC70 | 01/2010-12/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | XC70 | 01/2008-12/2009 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | XC70 | 01/2003-12/2007 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Volvo | XC70 | 01/2003-12/2007 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Volvo | XC90 | 01/2016-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | XC90 | 01/2015-12/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Volvo | XC90 | 01/2008-12/2008 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | XC90 | 01/2004-12/2014 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Volvo | XC90 | 01/2003-12/2007 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |