

Update Log

Date: Sep.-25-2008

Item: EPB101 Software V1.01

Why update?

1. V1.00 EPB101 may not be able to close brake pads on Mercedes Benz E211 SBC and E219 SBC after changing pads.

Solutions:

1. Fixed problems associated with Mercedes Benz E211 SBC and E219 SBC by improving command transmitting methods.