

## **MaxiSys GreatWall V3.96 2016-12-20**

1. Fixed an issue that caused function abnormal in ABS for Cowry, Great Wall V80, Haval H3, Wingle, Cool Bear, Haval M2, Haval M5, etc.